

Figure - Bug #114222

测试 Test-IT # 110867 (New): V1.0测试功能汇总

测试 Test-IT # 110895 (New): AF-V1.0功能测试-桌面

【AF】【EVT】【图库】在图片或视频界面点击蓝牙分享按钮，会打开一个新的后台，且无法连接设备进行分享

2022-11-30 16:54 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-11-30
Priority:	High	Due date:	2022-12-15
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:	MCE_V4.0update_20221215(原VC1_FSE_Vdec1219)	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0052.X
Need_Info:	--	Degrated:	--
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Severity:	Normal	Fixed Version:	2022-12-09
Reproducibility:	Every time	Root cause:	AOSP问题
Test Type:	IT		
Description			
【前提条件】			
1、设备已开机			
2、本地有图片或视频			
【测试步骤】			
1、打开图库应用			
2、选择一张图片或视频			
3、点击右上角的蓝牙图标			
4、进recent查看			
【预期结果】			
4、待确认			
【实际结果】			
4、除图库外有一个单独的蓝牙进程卡片			

History

- #1 - 2022-12-05 17:31 - CD APP-王营
- Due date set to 2022-12-15
- #2 - 2022-12-05 17:39 - CDTs-TEST 周婷
- Target version set to MCE_V4.0update_20221215(原VC1_FSE_Vdec1219)
- #3 - 2022-12-05 19:16 - CD APP-王营
- Status changed from New to ASSIGNED
- Assignee changed from CD APP- 王营 to CD APP- 黄棚
- #4 - 2022-12-07 09:38 - CD APP-李德盛
- Assignee changed from CD APP- 黄棚 to CD APP- 李德盛
- #5 - 2022-12-07 09:43 - CD APP-李德盛
- Assignee changed from CD APP- 李德盛 to CD APP- 黄棚

#6 - 2022-12-07 11:07 - CD APP-王营
- Assignee changed from CD APP-黄棚 to CD LC 陶洪普

从桌面手势下滑进入控制中心，点击屏幕截图，点击分享，选择蓝牙，跳转到蓝牙列表后无法加载出蓝牙设备列表。
请LC同事帮忙分析一下这个问题。

#7 - 2022-12-07 11:35 - CD APP-黄棚

■ Current conclusion
类似的问题打印菜单隐藏
■ My analysis
没必要的功能
■ Submit URL
<https://dev.thundercomm.com/gerriit/c/general/platform/packages/apps/Gallery2/+168190>

#8 - 2022-12-07 12:47 - CD LC 陶洪普

Hi 方永红,

需求是设备只能连接耳机，键盘，鼠标，手柄。这类设备是不具备图片，文件分享功能的。
因此不能做文件分享。不支持OOP传输。

【预期结果】
4、待确认

请明确预期结果。谢谢！
(请参照上面解释说明，明确预期结果)

#9 - 2022-12-07 12:49 - CD LC 陶洪普
- Status changed from ASSIGNED to NEED_INFO
- Assignee changed from CD LC 陶洪普 to CD TEST-方永红

#10 - 2022-12-07 15:37 - CD TEST-方永红
- Status changed from NEED_INFO to ASSIGNED
- Assignee changed from CD TEST-方永红 to CD APP-王营

#11 - 2022-12-08 12:58 - CD APP-黄棚
- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD APP-王营 to CD APP-黄棚
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Fixed Version set to 2022-12-09
- Root cause set to AOSP问题

■ Current conclusion
去掉无用的功能
■ My analysis

去掉相关无用的功能，如打印分享、蓝牙分享、时钟应用的屏保等

■ Submit URL

- <https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Gallery2/+168190>
- <https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Gallery2/+168514>
- <https://dev.thundercomm.com/gerrit/c/general/platform/vendor/qcom-opensource/packages/apps/Bluetooth/+168304>
- <https://dev.thundercomm.com/gerrit/c/general/platform/packages/services/BuiltInPrintService/+168544>
- <https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/DeskClock/+168340>
- <https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Gallery2/+168319>
- <https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Gallery2/+168190>

#12 - 2022-12-08 18:25 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
168190	general/platform/packages/apps/Gallery2	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpeng1216@thundersoft.com
FW: Gallery2: Hide print1. hide printTC-RID: 1201-0300701IssueID: TS-R-BUG-114222Change-Id: Iec69ef4f0bd72cef353697efab859e6ba5f7e87d			

#13 - 2022-12-08 18:25 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
168319	general/platform/packages/apps/Gallery2	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpeng1216@thundersoft.com
FW: Gallery2: Hide settings1. hide settingsTC-RID: 1201-0300701IssueID: TS-R-BUG-114222Change-Id: I05414bdfa2f35775f371baeb94ee52d35716a108			

#14 - 2022-12-08 18:26 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
168514	general/platform/packages/apps/Gallery2	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpeng1216@thundersoft.com
FW: Gallery2: Hide setas1. hide setasTC-RID: 1201-0300701IssueID: TS-R-BUG-114222Change-Id: I5601753c90aedc7f478ea0d120b0808ee3ffc03b			

#15 - 2022-12-08 18:26 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
168340	general/platform/packages/apps/DeskClock	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpeng1216@thundersoft.com

FW: DeskClock: Hide clock screensaver1. hide clock screensaverTC-RID: 1201-0300901IssueID: TS-R-BUG-114222Change-Id: Id1102a8327d29dad9495b90b565a0b34a89c4241

#16 - 2022-12-08 18:26 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
168544	general/platform/packages/services/BuiltInPrintService	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpeng1216@thundersoft.com
FW: BuiltInPrintService: Disable print sharing1. Disable print sharingTC-RID: 1201-0207501IssueID: TS-R-BUG-114222Change-Id: I8b8d39655e90bc6c8df074f33563029780b1a9ae			

#17 - 2022-12-08 18:26 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
168304	general/platform/vendor/qcom-opensource/packages/apps/Bluetooth	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpeng1216@thundersoft.com
FW: Bluetooth: Disable Bluetooth sharing1. Disable Bluetooth sharingTC-RID: 1201-0301401IssueID: TS-R-BUG-114222Change-Id: Ifba7fb2a3620803d924e43fe27944ab0d0077f49			

#18 - 2022-12-08 21:41 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
168533	general/platform/packages/apps/SnapdragonMusic	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpeng1216@thundersoft.com
FW: SnapdragonMusic: Fix sharing crash1. Fix music and video sharing crashTC-RID: 1201-0301201IssueID: TS-R-BUG-114222Change-Id: Ib7e1bc2999967bf580a440c62e701bc5346de18b			

#19 - 2022-12-09 10:25 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202212090644

#20 - 2022-12-09 10:27 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

#21 - 2022-12-13 09:50 - CD APP-黄棚

- Current conclusion
 - 时钟屏保微件移除
 - My analysis
 - 无用的功能
 - Submit URL
- <https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/DeskClock/+169721>

#22 - 2022-12-13 17:06 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
169721	general/platform/packages/apps/DeskClock	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	huangpeng1216@thundersoft.com
FW: DeskClock: Hide clock screensaver widget1. hide clock screensaver widgetTC-RID: 1201-0300901IssueID: TS-R-BUG-114222Change-Id: I0773363b5b7fe08c70f37fa7447877ebee1c57b			

#23 - 2022-12-14 14:27 - CD APP-黄棚

- Assignee changed from CD APP-黄棚 to CD TEST-方永红

Files			
Phone-STS40X190142 2022-11-30 16-43-01.mp4	21.3 MB	2022-11-30	CD TEST-方永红