

Figure - Bug #114458

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT】【设置】点击应用-查看全部应用页面右上角的搜索按钮，设置崩溃

2022-12-09 16:48 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-12-09
Priority:	High	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Severity:	Major	Fixed Version:	2022-12-09
Reproducibility:	Every time	Root cause:	因 UI 适配移除组件不完全导致的崩溃。
Test Type:	IT		
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1、进入设置-应用-查看全部应用页面			
2、点击页面右上角的搜索按钮			
【预期结果】			
2、可对下面的列表进行搜索			
【实际结果】			
2、点击之后闪退回主页面，重复操作，设置崩溃			
PS:设置内有该搜索图标的地方，点击之后都会崩溃			
具体见截图			

History

#1 - 2022-12-09 18:50 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
169054	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Fix click toolbar search view crash.TC-RID: 1201-0201813IssueID: TS-R-BUG-114458Change-Id: I5a0a0fe0488f79274a5a14ceec61855c278a83e5			

#2 - 2022-12-09 18:52 - CD FW-廖涛

- Assignee changed from CD FW-廖涛 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2022-12-09

■ Current conclusion

已修复，提交：<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Settings/+169054>

■ My analysis

因 UI 适配移除组件不完全导致的崩溃。

■ Next action

测试验证。

#3 - 2022-12-12 09:55 - CD FW-廖涛

- Status changed from New to RESOLVED

#4 - 2022-12-12 11:07 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED

- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202212090644

12.12

验证关闭

#5 - 2022-12-12 11:07 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

#6 - 2022-12-21 16:08 - CD FW-廖涛

- Root cause set to 因 UI 适配移除组件不完全导致的崩溃。

Files

Phone-ST\$40X190122 2022-12-09 16-25-05.mp4	13.7 MB	2022-12-09	CD TEST-方永红
logcat16.txt	4.69 MB	2022-12-09	CD TEST-方永红
搜索2.png	248 KB	2022-12-09	CD TEST-方永红
搜索按钮.png	227 KB	2022-12-09	CD TEST-方永红