

Figure - Bug #114515

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT】【设置】在应用不在通知白名单的情况下，能够在设置-应用-通知页面对应用通知设置进行开关

2022-12-12 18:06 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-12-12
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Severity:	Normal	Fixed Version:	2022-12-13
Reproducibility:	Every time	Root cause:	应用通知设置没有过滤白名单和系统应用，现在把
Test Type:	IT		
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1、进入设置-应用页面			
2、在最近打开的应用中，随机选择一个			
3、点击通知			
4、观察出现的页面			
【预期结果】			
4、页面中的通知开关按钮被锁定，无法开关			
【实际结果】			
4、能够在应用-通知页面对应用通知设置进行开关			

History

- #1 - 2022-12-13 09:57 - CD FW 曹覃刚
- Status changed from New to ASSIGNED
- Assignee changed from CD FW 曹覃刚 to CD FW-程天颖
- #2 - 2022-12-13 16:31 - CD FW-程天颖
- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW-程天颖 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution deleted (--)
- Degrated changed from -- to No
- Fixed Version set to 2022-12-13
- Root cause set to 乐播投屏在SDK初始化时,注册服务监听回调事件.验证SKD服务,根据官方文档解释:乐播投屏SDK需要License认证才能使用。在第一步SDK集成之后,必须设置License认证接口(设置服务发布状态监听),否则正常使用投屏功能。如果license校验失败,会在ServerListener的回调方法里收到相关信息.在收到信息后乐播投屏会使用Toast展示连接信息,由于prd没有此要求,所有把toast换为Log
- #3 - 2022-12-13 19:11 - CD FW-程天颖
- Status changed from RESOLVED to ASSIGNED

- Assignee changed from CD TEST- 方永红 to CD FW-程天颖
- % Done changed from 100 to 40
- Degrated deleted (No)
- Root cause deleted (乐播投屏在SDK初始化时,注册服务监听回调事件.验证SKD服务,根据官方文档解释.乐播投屏SDK需要License认证才能使用。在第一步SDK集成之后,必须设置License认证接口(设置服务发布状态监听),否则正常使用投屏功能。如果license校验失败,会在ServerListener的回调方法里收到相关信息.在收到信息后乐播投屏会使用Toast展示连接信息,由于prd没有此要求,所有把toast换为Log)

#4 - 2022-12-13 19:36 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
169918	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tianying.cheng@thundersoft.com
AF:Settings:Fixed the Notifications page toggles app notification settings on and offTC-RID: 1201-0201803IssueID: TS-R-BUG-114515Change-Id: I270f1e9276cc81bd842418da9e886c8bd8a7bb87			

#5 - 2022-12-13 19:50 - CD FW-程天颖

- Assignee changed from CD FW-程天颖 to CD TEST-方永红
- % Done changed from 40 to 100
- Degrated set to No
- Root cause set to 应用通知设置没有过滤白名单和系统应用, 现在把没有在白名单的三方应用的通知设置入口隐藏了

■ Current conclusion

Bug is Fixed

■ My analysis

应用通知设置没有过滤白名单和系统应用, 现在把没有在白名单的三方应用的通知设置入口隐藏了

■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Settings/+/169918>

#6 - 2022-12-13 19:52 - CD FW-程天颖

- Status changed from ASSIGNED to RESOLVED
- Resolution set to FIXED

#7 - 2022-12-16 19:01 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202212160615

12.16

非系统应用、通知白名单的应用无法进行通知开关（原生情况除外）

#8 - 2022-12-16 19:01 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files

11111111111111111111.jpg	215 KB	2022-12-12	CD TEST-方永红
--------------------------	--------	------------	-------------