

Figure - Bug #114538

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT】【设置】网络与互联网-wlan开关，打开关闭时有明显卡顿现象

2022-12-13 16:04 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-12-13
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	0%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V5.0_20221230	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0057.X
Need_Info:	--	Degrated:	--
Resolution:	WONTFIX	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	
Test Type:	IT		

Description
【前提条件】 1、设备已开机 【测试步骤】 1、进入设置-网络与互联网页面 2、重复点击wlan开关 【预期结果】 3、开关流畅 【实际结果】 3、打开关闭时有明显卡顿现象

History

- #1 - 2022-12-13 16:17 - CD FW 曹覃刚
- Status changed from New to ASSIGNED
- Assignee changed from CD FW-廖涛 to CD FW-程天颖
- #2 - 2022-12-14 19:03 - CDTs-TEST 周婷
- Target version set to VX1_MCE_FSE_V5.0_20221230
- #3 - 2022-12-16 16:20 - CD FW 曹覃刚
- Category changed from CD-FW to 依赖UI/UE
- Assignee changed from CD FW-程天颖 to 方案组-RD3_CDTs 王浩云
- Hi 浩云
- 目前wifi的式样尚未明确
- 等客户正式输入后，请告知
- 感谢
- #4 - 2022-12-16 17:01 - 方案组-RD3_CDTs 王浩云
- Assignee changed from 方案组-RD3_CDTs 王浩云 to CD FW 曹覃刚

请优化控制中心开关状态的切换平滑度，至少不应该出现卡顿现象，此处的UI已提供

#5 - 2022-12-16 17:07 - 方案组-RD3_CDTs 王浩云
- Category changed from 依赖UI/UE to CD-FW

相关开关的打开/关闭切换的优化，都需要考虑，不仅仅WiFi

#6 - 2022-12-27 16:57 - CD TPM-王祥林
- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW 曹覃刚 to CD TEST-方永红
- Resolution changed from -- to WONTFIX

永红

根据下面的最新需求，整个网络菜单都会删除掉。所以这个票不用处理了。
<https://share.thundersoft.com/redmine/issues/114797>
如果发现有其他开关卡顿的情况，另外起票跟踪吧。

#7 - 2022-12-27 17:56 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED

#8 - 2022-12-27 17:56 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

Files			
Phone-STS40X190122 2022-12-13 15-58-40.mp4	13.2 MB	2022-12-13	CD TEST-方永红