

Figure - Bug #114566

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT】【设置】从控制中心或者通知中心进入设置，设置页面上下端，有明显的白边闪烁现象

2022-12-14 15:47 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-12-14
Priority:	Normal	Due date:	2023-01-13
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0058.X
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Reproducibility:	Every time	Fixed Version:	2023-01-16
Test Type:	IT	Root cause:	原生UI适配

Description	
【前提条件】	
1、设备已开机	
【测试步骤】	
1、下划打开控制中心	
2、长按蓝牙选项进入	
【预期结果】	
2、正常进入设置，页面无闪烁等现象	
【实际结果】	
2、设置页面上下端，有明显的白边闪烁现象	

History

- #1 - 2022-12-14 16:37 - CD FW 曹覃刚
- Status changed from New to ASSIGNED
- Assignee changed from CD FW-廖涛 to CD FW-程天颖
- #2 - 2022-12-14 19:02 - CDTs-TEST 周婷
- Target version set to VX1_MCE_FSE_V5.0_20221230
- #3 - 2022-12-19 10:25 - CD FW-鲁凯峰
- Assignee changed from CD FW-程天颖 to CD FW-鲁凯峰
- #4 - 2022-12-20 10:45 - CD FW-程天颖
- Assignee changed from CD FW-鲁凯峰 to CD FW-程天颖
- #5 - 2022-12-22 16:40 - CD FW-王伟
- Target version changed from VX1_MCE_FSE_V5.0_20221230 to VX1_MCE_FSE_C sample_20230113
- #6 - 2022-12-22 16:44 - CD FW-王伟
- Assignee changed from CD FW-程天颖 to CD FW-鲁凯峰
- #7 - 2022-12-27 17:25 - CD FW 曹覃刚

- Assignee changed from CD FW-鲁凯峰 to CD FW 曹覃刚

#8 - 2023-01-06 10:17 - CD FW 曹覃刚

- Assignee changed from CD FW 曹覃刚 to CD FW-廖涛

#9 - 2023-01-11 16:23 - CDTS-TEST 周婷

- Due date set to 2023-01-13
- Target version deleted (VX1_MCE_FSE_C sample_20230113)

#10 - 2023-01-12 14:15 - CD FW 曹覃刚

- Assignee changed from CD FW-廖涛 to CD FW 曹覃刚

#11 - 2023-01-13 16:48 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
175668	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Fix system bar white background problem.TC-RID: 1201-0201813IssueID: TS-R-BUG-114566Change-Id: I6565e34db24bd8337e0f19b3d857ac291b9e8f3b			

#12 - 2023-01-13 16:51 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
176350	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com
AF:Theme: modify splash window background color and overview backgroundcolorTC-RID: 1201-0202101IssueID: TS-R-BUG-114566Change-Id: I4d2f45c33d0520d2aee6795c718cda4a90c9d9a6			

#13 - 2023-01-13 16:52 - CD FW 曹覃刚

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW 曹覃刚 to CD TEST-方永红
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-01-16
- Root cause set to 原生UI适配

#14 - 2023-01-16 14:09 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- % Done changed from 0 to 100
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202301161238

1.16
验证通过

#15 - 2023-01-16 14:09 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

Files			
Phone-STS40X190122 2022-12-14 15-43-55.mp4	20.3 MB	2022-12-14	CD TEST-方永红