

Figure - Bug #114655

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111051 (New): AF-V2.0-Launcher/SystemUI-通知中心

【AF】【EVT】【通知中心】向左滑动系统消息，等待设备进入屏保，唤醒设备后，通知中心中消息主体旁边的设置按钮消失

2022-12-16 17:42 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-12-16
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0066.X
Severity:	Normal	Fixed Version:	2023-01-05
Reproducibility:	Every time	Root cause:	在息屏收起通知中心的同时，将通知菜单也收起
Test Type:	IT		
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1、打开通知中心			
2、向左滑动系统消息			
3、等待设备自然进入屏保			
4、唤醒设备			
5、下划打开通知中心			
【预期结果】			
4、小窗以圆角状态移动到屏幕右边			
【实际结果】			
4、通知中心中消息主体旁边的设置按钮消失			

History

#1 - 2022-12-23 17:43 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
171950	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Notification: Fix the problem that the notification menu disappears abnormallyWhen the notification center is collapsedthe notification menu also needs to be collapsedTC-RID: 1201-0201902IssueID: TS-R-BUG-114655Change-Id: I03d2f0f9ac6ef020180b6a537ea25f1902287ec5			

#2 - 2022-12-23 17:45 - CD FW 曹覃刚

- Status changed from New to RESOLVED

- Assignee changed from CD FW 曹覃刚 to CD TEST- 方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2022-12-26
- Root cause set to 在息屏收起通知中心的同时，将通知菜单也收起

- #3 - 2022-12-28 11:06 - CD TEST-方永红
- Status changed from RESOLVED to VERIFY_FAILED
 - Assignee changed from CD TEST- 方永红 to CD FW 曹覃刚

12.28

验证失败

#4 - 2023-01-03 20:20 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
173803	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Notification: Fix the problem that the notification menu disappears abnormally1.Remove custom reset method2.Change the aosp X-translation method to our ownTC-RID: 1201-0201902IssueID: TS-R-BUG-114655Change-Id: Ib495d63bc4642fdac7923b08b09b10b87bdb7860			

- #5 - 2023-01-04 09:40 - CD FW 曹覃刚
- Status changed from VERIFY_FAILED to RESOLVED
 - Assignee changed from CD FW 曹覃刚 to CD TEST- 方永红
 - Fixed Version changed from 2022-12-26 to 2022-12-05

- #6 - 2023-01-04 09:40 - CD FW 曹覃刚
- Fixed Version changed from 2022-12-05 to 2023-01-05

- #7 - 2023-01-05 11:01 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED
 - Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0066.X101

1.5

验证通过

- #8 - 2023-01-05 11:01 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

Files			
1741.png	236 KB	2022-12-16	CD TEST-方永红