

Status:	CLOSED	Start date:	2022-12-16
Priority:	High	Due date:	
Assignee:	CDTS_TEST 刘勇	% Done:	0%
Category:	BSP	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V5.0_20221230	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Need_Info:	--	Degrated:	--
Resolution:	--	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	
Test Type:	IT		
Description			
【前提条件】 1.中控环境搭建好 2.中控环境中全量包 【测试步骤】 3.中控通过网线链接路由，路由通过网线或者wifi 链接DUT 4.中控IP：192.168.0.2，DUT-IP：192.168.0.18 5.进入终端，cd ~/server/目录，并运行命令 sudo ./run_https.sh sudo ./run_orch.sh adb shell logcat > logcat-screnen-not_black.txt 6.待功能启动 7.选择功能2（Download PACKAGE） 输入"2"->按"回车" ->输入"1"->输入"update.zip" 8.等待下载完成并选择运行功能0（run script） 输入"0"->按"回车"->等待log中有提示下载完成(download succesful)->“adb reboot” 9.等待升级完成后，运行功能1(Rollback) 输入“1” ->按“回车” -->等待提示"rollback done 100% ,done" ->"adb reboot" 【期望结果】 9.回滚成功 【实际结果】 4.回滚失败			
Related issues:			
Copied from Figure - Bug # 114663: 【BSP】【EVT2】【FOTA】副屏接收包...		CLOSED	2022-12-16

History

- #1 - 2022-12-22 10:51 - CD BSP 叶鹏
- Status changed from New to NEED_INFO
- Assignee changed from CD BSP 叶鹏 to BPD-TMBG 刘勇

操作方式存在错误：

升级成功在重启之前是不会切换slot的，需要升级成功且重启设备之后，才能执行回滚的操作：

在升级之前检查slot；

在升级成功且重启设备之后，需要查看切换之后的slot
然后执行回滚命令之后，需要重启设备，设备重启之后再次检查回滚之后的slot

#2 - 2022-12-22 17:25 - CDTS-TEST 周婷
- Assignee changed from BPD-TMBG 刘勇 to CDTS_TEST 刘勇

#3 - 2022-12-27 22:55 - CDTS_TEST 刘勇

测试人员操作失误，需要重启升级成功后回滚，关闭此单

#4 - 2022-12-30 10:38 - CDTS_TEST 刘勇
- Status changed from NEED_INFO to RESOLVED

#5 - 2022-12-30 10:38 - CDTS_TEST 刘勇
- Status changed from RESOLVED to VERIFIED

#6 - 2022-12-30 10:38 - CDTS_TEST 刘勇
- Status changed from VERIFIED to CLOSED

Files			
logcat-boxes-fota-dut_screen_not_poweroff.txt	3.38 MB	2022-12-16	CDTS_TEST 刘勇
logcat-boxes-fota-dut_rollback_fail.txt	2.23 MB	2022-12-16	CDTS_TEST 刘勇