

Figure - 开发 Dev #114683

开发 Dev # 110122 (New): 【MK】管理总票

开发 Dev # 110126 (New): 【MK】【AF】管理总票

【MK】【AF】【测试工具】【TC-RID: 1201-0204501】

2022-12-19 11:50 - CD TPM-王祥林

Status:	完成 Closed	Start date:	2022-12-19
Priority:	Normal	Due date:	
Assignee:	CD TPM-王祥林	% Done:	100%
Category:		Estimated time:	0.00 hour
Target version:			
Description			

History

#1 - 2022-12-19 19:14 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
171063	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-ftm-dvt1	wangxl0510@thundersoft.com
FW: Launcher: Start BurnInTest Application for factory test.Start BurnInTest Application for factory test.TC-RID: 1201-0201002IssueID: TS-R-DF-114683Change-Id: If527f615eca8aed6e7d86cfc75844f0b733252ef			

#2 - 2022-12-19 19:15 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
171131	general/platform/vendor/thundercomm/apps/FactoryTest	Pre_figure_turbox-c2130c-la1.1-qssi12-ftm-dvt1	wangxl0510@thundersoft.com
FW: FactoryTest: Add BurnInTest Application for factory test.Add BurnInTest Application for factory test.TC-RID: 1201-0201002IssueID: TS-R-DF-114683Change-Id: I275a70ce676d64f310eb0448ed676f691408291f			

#3 - 2022-12-20 11:08 - CD TPM-王祥林

- Subject changed from 【MK】【AF】【工厂老化apk】【TC-RID: 1201-0201002】 to 【MK】【AF】【工厂测试】【TC-RID: 1201-0201002】

#4 - 2022-12-20 11:25 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
171232	general/platform/vendor/thundercomm/apps/TCService	Pre_figure_turbox-c2130c-la1.1-qssi12-ftm-dvt1	wangxl0510@thundersoft.com

FW: FactoryTest: Disable MCU auto update.Don't send update message to mcu in ftm branch.TC-RID: 1201-0201002IssueID: TS-R-DF-114683Change-Id: Iccce214719412ca27b8d65b8adf75fecf71611a3

#5 - 2022-12-26 10:17 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
172143	general/platform/vendor/thundercom m/apps/FactoryTest	Pre_figure_turbox-c2130c-la1.1-qssi12 -ftm-dvt1	wangxl0510@thundersoft.com
FW: FactoryTest: Modify logic of running BurnInTest Application for factory test.If test result exist, do not run again.TC-RID: 1201-0201002IssueID: TS-R-DF-114683Change-Id: Iecd838d42d9b02f373e96862fe8c4d00a10789b4			

#6 - 2023-01-16 19:47 - CD TPM-王祥林

- Assignee set to CD TPM-王祥林

#7 - 2023-01-16 19:47 - CD TPM-王祥林

- Status changed from New to 完成 Closed

- % Done changed from 0 to 100

#8 - 2023-02-13 17:23 - CD TPM-王祥林

- Subject changed from 【MK】 【AF】 【工厂测试】 【TC-RID: 1201-0201002】 to 【MK】 【AF】 【测试工具】 【TC-RID: 1201-0204501】

#9 - 2023-02-13 17:30 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
181361	general/platform/vendor/thundercom m/apps/FOTA	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	wangxl0510@thundersoft.com
AF: TestTools: Add some new functions in test application.1.Delete MCU upgrade function.2.Add IDCM audio control function.3.Add reboot function.TC-RID: 1201-0204501IssueID: TS-R-DF-114683Change-Id: I414f71c72072ea78791292fd391edfed7de59a84			

#10 - 2023-02-28 00:56 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
184208	general/platform/vendor/thundercom m/apps/TestTools	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	wangxl0510@thundersoft.com
AF: TestTools: Move source code from McuUpdate to TestToolsTC-RID: 1201-0204501IssueID: TS-R-DF-114683Change-Id: I2cd0be49dcb50e61e93bec8a6b3bdc797cbcc693			

#11 - 2023-02-28 00:56 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
184207	general/platform/vendor/thundercom m/apps/FOTA	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	wangxl0510@thundersoft.com
AF: TestTools: Move source code from McuUpdate to TestToolsTC-RID: 1201-0204501IssueID: TS-R-DF-114683Change-Id: la32f2a14550ff1be656f1a59a2943cd647a06926			

#12 - 2023-02-28 00:57 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
184206	general/platform/packages/apps/Settin gsIntelligence	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	wangxl0510@thundersoft.com
AF: TestTools: Move source code from McuUpdate to TestToolsTC-RID: 1201-0204501IssueID: TS-R-DF-114683Change-Id: I9dc65e2e3da0284d8a53a0376f1c6026bbd3ab34			

#13 - 2023-02-28 00:57 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
184205	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	wangxl0510@thundersoft.com
AF: TestTools: Move source code from McuUpdate to TestToolsTC-RID: 1201-0204501IssueID: TS-R-DF-114683Change-Id: I2eb857533035bf3f113056236364556e6b70f807			

#14 - 2023-03-02 09:39 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
184941	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	wangxl0510@thundersoft.com
AF: TestTools: Add Engineer mode for debugging.Add Engineer mode interface.TC-RID: 1201-0204501IssueID: TS-R-DF-114683Change-Id: la8136ec3c161dc272159bb59ec0709e23511a202			

#15 - 2023-03-10 14:02 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
186880	general/platform/vendor/thundercom	Pre_figure_turbox-c2130c-la1.1-qssi12	wangxl0510@thundersoft.com

	m/apps/TestTools	-ftm_v0081	
AF: TestTools: Add Engineer mode in test tools.TC-RID: 1201-0204501IssueID: TS-R-DF-114683Change-Id: Id6e2b61f8f2e21a3379246a401692dd3880b847c			

#16 - 2023-03-10 14:15 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
186785	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-ftm_v0081	wangxl0510@thundersoft.com
FW: Launcher: Start BurnInTest Application for factory test.Start BurnInTest Application for factory test.TC-RID: 1201-0201002IssueID: TS-R-DF-114683Change-Id: If527f615eca8aed6e7d86cfc75844f0b733252ef(cherry picked from commit df4b085fb00d1e7adb43eefa5e76ab030d38f11a)			

#17 - 2023-03-10 14:56 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
186787	general/platform/vendor/thundercomm/apps/TCService	Pre_figure_turbox-c2130c-la1.1-qssi12-ftm_v0081	wangxl0510@thundersoft.com
FW: FactoryTest: Disable MCU auto update.Don't send update message to mcu in ftm branch.TC-RID: 1201-0201002IssueID: TS-R-DF-114683Change-Id: Iccce214719412ca27b8d65b8adf75fecf71611a3(cherry picked from commit f623925bde3bc2a7612700233209f3d5e84f389c)			

#18 - 2023-03-14 19:53 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
185246	general/platform/vendor/thundercomm/apps/TestTools	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	wangxl0510@thundersoft.com
AF: TestTools: Add Engineer mode in test tools.TC-RID: 1201-0204501IssueID: TS-R-DF-114683Change-Id: Id6e2b61f8f2e21a3379246a401692dd3880b847c			

#19 - 2023-04-16 11:26 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
193972	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-ftm_v0090	wangxl0510@thundersoft.com

FW: Launcher: Start BurnInTest Application for factory test.Start BurnInTest Application for factory test.TC-RID: 1201-0201002IssueID:
TS-R-DF-114683Change-Id: If527f615eca8aed6e7d86cfc75844f0b733252ef(cherry picked from commit df4b085fb00d1e7adb43eefa5e76ab030d38f11a)(cherry
picked from commit c6ebe5d14a8a75af4af5abe39ed3a4bbb6b835fe)

#20 - 2023-04-16 11:27 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
193969	general/platform/vendor/thundercom m/apps/TCService	Pre_figure_turbox-c2130c-la1.1-qssi12 -ftm_v0090	wangxl0510@thundersoft.com
FW: FactoryTest: Disable MCU auto update.Don't send update message to mcu in ftm branch.TC-RID: 1201-0201002IssueID: TS-R-DF-114683Change-Id: Iccce214719412ca27b8d65b8adf75fecf71611a3(cherry picked from commit f623925bde3bc2a7612700233209f3d5e84f389c)(cherry picked from commit 93dfcc500698718902be695ad1f37695d88afb69)			

#21 - 2023-05-03 16:34 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
197291	general/platform/vendor/thundercom m/apps/TCService	Pre_figure_turbox-c2130c-la1.1-qssi12 -ftm_v0095	wangxl0510@thundersoft.com
FW: FactoryTest: Disable MCU auto update.Don't send update message to mcu in ftm branch.TC-RID: 1201-0201002IssueID: TS-R-DF-114683Change-Id: Iccce214719412ca27b8d65b8adf75fecf71611a3(cherry picked from commit f623925bde3bc2a7612700233209f3d5e84f389c)(cherry picked from commit 93dfcc500698718902be695ad1f37695d88afb69)(cherry picked from commit c403f47b39697cc368de1d671a9c652fe99108f6)			

#22 - 2023-05-03 16:34 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
197285	general/platform/packages/apps/Launc her3	Pre_figure_turbox-c2130c-la1.1-qssi12 -ftm_v0095	wangxl0510@thundersoft.com

FW: Launcher: Start BurnInTest Application for factory test.Start BurnInTest Application for factory test.TC-RID: 1201-0201002IssueID:
TS-R-DF-114683Change-Id: If527f615eca8aed6e7d86cfc75844f0b733252ef(cherry picked from commit df4b085fb00d1e7adb43eefa5e76ab030d38f11a)(cherry
picked from commit c6ebe5d14a8a75af4af5abe39ed3a4bbb6b835fe)(cherry picked from commit 0aa558df43311ecb46cbc166026202b6a80b5a4c)

#23 - 2023-05-19 21:03 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
200288	general/platform/vendor/thundercom m/apps/TestTools	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	wangxl0510@thundersoft.com
AF: TestTools: Add some tips for OTA.TC-RID: 1201-0204501IssueID: TS-R-DF-114683Change-Id: I8c73a73a0135692705f85ec73dfe430eedd73619			

#24 - 2023-06-21 11:25 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
208999	general/platform/vendor/thundercom m/apps/TestTools	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	wangxl0510@thundersoft.com
AF: TestTools: Modify tips for debug mode.TC-RID: 1201-0204501IssueID: TS-R-DF-114683Change-Id: I5721096b60affed401c9500cb32786357568fd38			

#25 - 2023-06-25 21:40 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
209671	general/platform/vendor/thundercom m/apps/TestTools	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF: TestTools: Modify tips for debug mode.TC-RID: 1201-0204501IssueID: TS-R-DF-114683Change-Id: I5721096b60affed401c9500cb32786357568fd38(cherry picked from commit 2982c7033178794ff8b36d31e46a6d3693a08009)			

#26 - 2023-07-06 20:26 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
212799	general/platform/vendor/thundercom m/apps/TestTools	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF: TestTools: Hide audio control button and debug mode button.TC-RID: 1201-0204501IssueID: TS-R-DF-114683Change-Id: I120b45d07e31a5fc3700e71530ccaaf7c1c4a956			

#27 - 2023-07-06 21:27 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
212964	general/platform/vendor/thundercom m/apps/TestTools	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF: TestTools: Hide audio control button and debug mode button in user version.TC-RID: 1201-0204501IssueID: TS-R-DF-114683Change-Id: Icf6603761c03d8dd6691b30e71eec596eeda1d20e			

#28 - 2023-07-12 15:21 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
212241	general/platform/vendor/thundercom m/apps/TestTools	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	wangxl0510@thundersoft.com
AF: TestTools: Add sync operation and modify delay for OTA.TC-RID: 1201-0204501IssueID: TS-R-DF-114683Change-Id: I24a51a60c8321fa1367279490f898b4b8424b261			

#29 - 2023-07-12 20:20 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
214368	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com
AF: TestTools: change the attribute name of the debugging mode.TC-RID: 1201-0204501IssueID: TS-R-DF-114683Change-Id: I4921ed0baa72223c05b597a3c504819e7ae7eae9			

#30 - 2023-07-13 21:50 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
214746	general/platform/vendor/thundercom m/apps/TestTools	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF: TestTools: Add sync operation and modify delay for OTA.TC-RID: 1201-0204501IssueID: TS-R-DF-114683Change-Id: I24a51a60c8321fa1367279490f898b4b8424b261(cherry picked from commit 54963c03f56e7a1ca00129b0ad8d08dcbdd213fc)			

#31 - 2023-07-13 21:51 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
214748	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com

AF: TestTools: change the attribute name of the debugging mode.TC-RID: 1201-0204501IssueID: TS-R-DF-114683Change-Id: I4921ed0baa72223c05b597a3c504819e7ae7eae9(cherry picked from commit 57a7a0f744f66b2986108568fe3aacb53be06e4f)

#32 - 2023-07-18 20:03 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
215874	general/platform/vendor/thundercom m/apps/TestTools	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	wangxl0510@thundersoft.com
AF: TestTools: Add factory reset button in test tools.TC-RID: 1201-0204501IssueID: TS-R-DF-114683Change-Id: Ife004d828de5a4a32129287510ea3e19488c5b94			

#33 - 2023-07-18 20:09 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
215828	general/platform/vendor/thundercom m/apps/TestTools	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF: TestTools: Add factory reset button in test tools.TC-RID: 1201-0204501IssueID: TS-R-DF-114683Change-Id: Ife004d828de5a4a32129287510ea3e19488c5b94(cherry picked from commit c2887868a0cfcfe4fe1b37da35bf9b35412d285)			