

Figure - Bug #114743

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT】【应用】应用下的相关权限修改后，返回上层目录，其权限显示不会实时刷新修改

2022-12-22 10:38 - 物联网测试组_CDTS 段小刚

Status:	CLOSED	Start date:	2022-12-22
Priority:	Normal	Due date:	
Assignee:	物联网测试组_CDTS 段小刚	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0061
Resolution:	FIXED	Degraded:	No
Severity:	Normal	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0063.X
Reproducibility:	Every time	Fixed Version:	2022-12-26
Test Type:	IT	Root cause:	Settings 页面结构调整导致返回后没有刷新状态。

Description	
【前提条件】	
1、设备已开机	
【测试步骤】	
1、打开设置——> 应用——>特殊应用权限——>xxxxx	
2、选择一个应用 点击	
3、点击 应用信息里的 “ 赋予文件权限管理 “ 的按钮	
4、返回上一层，查看该应用权限	
【预期结果】	
4、权限已改变	
【实际结果】	
4、没有改变	
【复现率】	
3/3	

History

#1 - 2022-12-26 10:50 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
172094	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Fix app perimission state sync problem.TC-RID: 1201-0201802IssueID: TS-R-BUG-114743Change-Id: I56685f1266f720f21f10a2d90da8907d1a2e3ad4			

#2 - 2022-12-26 10:54 - CD FW-廖涛

- Status changed from New to RESOLVED

- Assignee changed from CD FW-廖涛 to 物联网测试组_CDTS 段小刚

- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2022-12-26
- Root cause set to Settings 页面结构调整导致返回后没有刷新状态。

■ Current conclusion

已解决。

■ My analysis

Settings 页面结构调整导致返回后没有刷新状态。

■ Next action

测试验证。

#3 - 2022-12-28 11:16 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0063.X101

12.28
验证通过

#4 - 2022-12-28 11:16 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

#5 - 2022-12-28 15:44 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
172668	general/platform/packages/apps/Settins	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:Settings: Fix NullPointerException when running monkey test.TC-RID: 1201-0201802IssueID: TS-R-BUG-114743Change-Id: Ia9195fdc3ea800b41add2f28a477bcd061137a			

Files

20221222-103818.jpg	67.3 KB	2022-12-22	物联网测试组_CDTS 段小刚
---------------------	---------	------------	-----------------