

Figure - Bug #114765

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114580 (New): 首次购车激活

【AF】【EVT2】【首次购车激活】刷机启动执行完购车激活步骤后断电再上电，开机后仍然显示购车激活画面

2022-12-23 11:30 - CD Test赵飞

Status:	CLOSED	Start date:	2022-12-23
Priority:	Normal	Due date:	2022-12-30
Assignee:	CD Test赵飞	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V5.0_20221230	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Need_Info:	--	Degrated:	No
Resolution:	INVALID	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	激活测试应该采用模拟中控或者中控激活，点击屏
Test Type:	ST		

Description			
【测试版本】 FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202212230238			
【前提条件】 1、设备首次刷机启动			
【测试步骤】 1、在首次购车激活页面正常执行激活步骤后进入桌面 2、设备断电 3、设备上电启动			
【预期结果】 3、设备正常启动后进入桌面			
【实际结果】 3、设备启动后又显示首次购车激活画面			
【备注】 首次开机到桌面后，立即断电再上电可复现，log暂时没有抓到			

History

#1 - 2022-12-23 18:20 - CD FW-程天颖
- Status changed from New to RESOLVED
- % Done changed from 0 to 100
- Resolution changed from -- to INVALID
- Degrated changed from -- to No
- Root cause set to 激活测试应该采用模拟中控或者中控激活，点击屏幕的方式可以跳过激活页面但是设备实际并未激活。

Current conclusion

无效bug

My analysis

激活测试应该采用模拟中控或者中控激活，点击屏幕的方式可以跳过激活页面但是设备实际并未激活。

■ Submit URL

无

#2 - 2022-12-23 18:21 - CD FW-程天颖

- Assignee changed from CD FW-程天颖 to CD Test赵飞

#3 - 2022-12-27 15:45 - CD Test赵飞

- Status changed from RESOLVED to VERIFIED

- % Done changed from 100 to 80

通过点击屏幕的方式只是跳过激活，实际上未激活设备
使用模拟app进行激活后，不复现此问题

#4 - 2022-12-27 15:45 - CD Test赵飞

- Status changed from VERIFIED to CLOSED

- % Done changed from 80 to 100