

Figure - Bug #114775

测试 Test-ST # 113421 (New): V4.0功能与专项测试

【BSP】【EVT1】【ST】【Tlog】Tlog中勾选tcpdump日志，点击stop后tlog中没有tcpdump日志生成

2022-12-23 16:34 - 移动测试一组_CDTs 刘强

Status:	CLOSED	Start date:	2022-12-23
Priority:	High	Due date:	2022-12-27
Assignee:	移动测试一组_CDTs 刘强	% Done:	100%
Category:	SYSTEM	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V5.0_20221230	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.userdebug.01.00.0
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Major	Fixed Version:	2023-01-09
Reproducibility:	Every time	Root cause:	使用apk抓取tcpdump的log，没有添加相应的selinux
Test Type:	ST		
Description			
【前提条件】			
None			
【测试步骤】			
1、设备烧机后，进入主界面			
2、通过*#147#打开tlog，选择tcpdump log后start			
3、等待一段时间后点击stop			
4、查看tlog文件中是否存在tcpdump log			
【预期结果】			
4. tcpdump log生成			
【实际结果】			
5. tcpdump log未生成			

History

- #1 - 2022-12-26 17:08 - CDTs-TEST 周婷
- Due date set to 2022-12-27
- Target version set to VX1_MCE_FSE_V5.0_20221230

#2 - 2022-12-27 19:18 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
171903	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hubing0803@thundersoft.com
system:log:add tcpdump selinuxadd tcpdump need selinuxTC-RID: 1200-0800102IssueID: TS-R-BUG-114775Change-Id: I07fcfcc64799665f42a84547eab35f8ac323c618			

#3 - 2022-12-27 19:22 - CD SYSTEM-夏旭

- Status changed from New to RESOLVED

- Assignee changed from CD SYSTEM-夏旭 to 移动测试一组_CDTS 刘强
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2022-12-27
- Root cause set to 使用apk抓取tcpdump的log，没有添加相应的selinux

■ Current conclusion

已处理。运行命令，有tcpdump的文件产生。

■ My analysis

使用apk抓取tcpdump的log，没有添加相应的selinux。

■ Next action

测试验证

#4 - 2022-12-28 15:41 - 移动测试一组_CDTS 刘强

- Status changed from RESOLVED to VERIFY_FAILED
- Assignee changed from 移动测试一组_CDTS 刘强 to CD SYSTEM-夏旭

验证版本：FlatBuild_HH_VX1_MCE_FSE.M.D.userdebug.01.00.X101.202212280332

验证结果：验证失败

点击stop后，在/data/manual/ 下有日志生成，pull /sdcard/tlog/的压缩包没有文件tcpdump日志

#5 - 2023-01-06 17:31 - CD SYSTEM-夏旭

userdebug版本已经没有问题，在修改user版本的selinux

#6 - 2023-01-09 16:00 - IoT scm

Gerrit Merge Information：

ID	Project	Branch	Uploader
174507	general/platform/vendor/thundercomm/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xu.xia@thundersoft.com
system:log:modify tcpdumpmodify tcpdump file from 600 to 666add tlogd.shTC-RID: 1200-0800102IssueID: TS-R-BUG-114775Change-Id: I95f2eaae36e9d2b31b334ef742536cb1fa40fc9c			

#7 - 2023-01-09 16:00 - IoT scm

Gerrit Merge Information：

ID	Project	Branch	Uploader
172916	general/device/thundercomm/TCDEV	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	xu.xia@thundersoft.com

system:log:add tcpdump selinuxadd tcpdump need selinuxTC-RID: 1200-0800102IssueID: TS-R-BUG-114775Change-Id: I080746776c570a278a9a8853d7ca0c764aae6821

#8 - 2023-01-09 16:01 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
174505	general/device/qcom/sepolicy_vndr	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xu.xia@thundersoft.com
system:log:modify tcpdumpmodify tcpdump file from 600 to 666add selinuxTC-RID: 1200-0800102IssueID: TS-R-BUG-114775Change-Id: I504df027a5b33571568de05ce29688964163c808			

#9 - 2023-01-09 16:01 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
174685	general/platform/vendor/thundercomm/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	xu.xia@thundersoft.com
system:log:modify tcpdumpmodify tcpdump file from 600 to 666add service tlogdsh to tlogd.rcTC-RID: 1200-0800102IssueID: TS-R-BUG-114775Change-Id: Icd626d69e207855320fba8bd8206c62d26dd8531			

#10 - 2023-01-09 16:01 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
174506	general/vendor/thundercomm/products/figure	Pre_figure_turbox-c2130c-la1.1-vendor-dev	xu.xia@thundersoft.com
system:log:modify tcpdumpmodify tcpdump file from 600 to 666add tlogd.sh to figure.mkTC-RID: 1200-0800102IssueID: TS-R-BUG-114775Change-Id: If43cca8a44fc85616d29b4f3025d80861de10d07			

#11 - 2023-01-09 16:15 - CD SYSTEM-夏旭

- Status changed from VERIFY_FAILED to RESOLVED
- Fixed Version changed from 2022-12-27 to 2023-01-09
- Root cause changed from 使用apk抓取tcpdump的log，没有添加相应的selinux to 使用apk抓取tcpdump的log，没有添加相应的selinux，tcpdump产生的文件权限为600，导致没有打包

■ Current conclusion

已处理。apk点击stop之后打包的压缩包包含tcpdump的文件

■ My analysis

tcpdump产生的文件权限为600，导致没有打包

■ Next action

测试验证

#12 - 2023-01-09 16:16 - CD SYSTEM-夏旭

- Assignee changed from CD SYSTEM-夏旭 to 移动测试一组_CDTS 刘强

#13 - 2023-01-13 16:56 - 移动测试一组_CDTS 刘强

验证版本：FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0068.X101

验证结果：验证通过

#14 - 2023-01-13 16:56 - 移动测试一组_CDTS 刘强

- Status changed from RESOLVED to VERIFIED

#15 - 2023-01-13 16:56 - 移动测试一组_CDTS 刘强

- Status changed from VERIFIED to CLOSED