

Figure - Bug #114776

测试 Test-ST # 113421 (New): V4.0功能与专项测试

【BSP】【EVT1】【ST】【Tlog】Tlog中勾选QXDM日志，点击stop后tlog中没有QXDM日志生成

2022-12-23 16:36 - 移动测试一组_CDTs 刘强

Status:	CLOSED	Start date:	2022-12-23
Priority:	High	Due date:	2022-12-27
Assignee:	移动测试一组_CDTs 刘强	% Done:	100%
Category:	SYSTEM	Estimated time:	0.00 hour
Target version:	VX1_MCE_FSE_V5.0_20221230	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.userdebug.01.00.0
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Major	Fixed Version:	2022-12-27
Reproducibility:	Every time	Root cause:	没有添加tlog_qxdm的bin文件，导致运行命令没有
Test Type:	ST		
Description			
【前提条件】			
None			
【测试步骤】			
1、设备烧机后，进入主界面			
2、通过*#147#打开tlog，选择QXDM log后start			
3、等待一段时间后点击stop			
4、查看tlog文件中是否存在QXDM log			
【预期结果】			
4. QXDM log生成			
【实际结果】			
5. QXDM log未生成			

History

- #1 - 2022-12-26 17:07 - CDTs-TEST 周婷
 - Due date set to 2022-12-27
 - Target version set to VX1_MCE_FSE_V5.0_20221230

#2 - 2022-12-27 19:17 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
171802	general/device/qcom/sepolicy_vndr	Pre_figure_turbox-c2130c-la1.1-vendor-dev	hubing0803@thundersoft.com
system:log:add tlog_qxdmadd tlog_qxdm need selinuxTC-RID: 1200-0800102IssueID: TS-R-BUG-114776Change-Id: Ib7517d003ed1bd74e59ca2da3aa0db5771db8021			

#3 - 2022-12-27 19:17 - IoT scm

Gerrit Merge Information :

--	--	--	--

ID	Project	Branch	Uploader
172327	general/platform/vendor/thundercomm/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-vendor-dev	hubing0803@thundersoft.com
system:log:add tlog_qxdmadd tlog_qxdm need filesTC-RID: 1200-0800102IssueID: TS-R-BUG-114776Change-Id: I312a69c9c52332de6a8e0d554f447d291ae5014d			

#4 - 2022-12-27 19:17 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
171765	general/vendor/thundercomm/products/figure	Pre_figure_turbox-c2130c-la1.1-vendor-dev	hubing0803@thundersoft.com
system:log:add tlog_qxdmmodify figure.mkTC-RID: 1200-0800102IssueID: TS-R-BUG-114776Change-Id: I711a94494d579c66957e263852dc544623373101			

#5 - 2022-12-27 19:17 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
171739	general/platform/vendor/thundercomm/apps/LogSystem	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hubing0803@thundersoft.com
system:log:add tlog_qxdmmodify tlog filesTC-RID: 1200-0800102IssueID: TS-R-BUG-114776Change-Id: Ic4e5787d5de029f49eeacd0d7fa534257f6ea24d			

#6 - 2022-12-27 19:19 - CD SYSTEM-夏旭

- Status changed from New to RESOLVED
- Assignee changed from CD SYSTEM-夏旭 to 移动测试一组_CDTS 刘强
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2022-12-27
- Root cause set to 没有添加tlog_qxdm的bin文件，导致运行命令没有相应文件产生。

■ Current conclusion

已处理。运行命令，有qxdm的文件产生。

■ My analysis

没有添加tlog_qxdm的bin文件，导致运行命令没有相应文件产生。

■ Next action

测试验证

#7 - 2022-12-28 15:39 - 移动测试一组_CDTs 刘强

- Status changed from RESOLVED to VERIFIED

验证版本：FlatBuild_HH_VX1_MCE_FSE.M.D.userdebug.01.00.X101.202212280332

验证结果：验证通过

点击stop后，在/data/manual/qxdm 下有日志生成，pull /sdcard/tlog/的压缩包也有文件生成

#8 - 2022-12-28 15:40 - 移动测试一组_CDTs 刘强

- Status changed from VERIFIED to CLOSED