

Figure - Bug #114912

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111049 (New): AF-V2.0-副屏遥控器

【AF】【EVT】【遥控器】多设备同时连接同一块屏幕，应该是最后连接的设备具备屏幕的控制权

2022-12-28 16:57 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-12-28
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0063.X
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Severity:	Normal	Fixed Version:	2023-01-03
Reproducibility:	Every time	Root cause:	当前的连接控制策略和需求不一致，按要求更改连
Test Type:	IT		
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1、两台手机与设备连接同一WIFI			
2、两台手机先后通过遥控器与设备连接（先连接的为手机1，后连接的为手机2）			
3、利用手机1调节音量			
4、利用手机2调节音量			
【预期结果】			
3、不能调节			
4、可以成功调节			
【实际结果】			
3、4：均可调节			

History

#1 - 2023-01-03 17:15 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
173359	general/platform/vendor/thundercom/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:RemoteControl: Client(Android) - Modify the connection rule1.Multiple devices are connected to the same screen at the same time, and the last connected device should have control of the screenTC-RID: 1201-0206002IssueID: TS-R-BUG-114912Change-Id: lae8653f0007a97e45a3ed904bea3bd86e44247a0			

#2 - 2023-01-03 17:15 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
173363	general/platform/vendor/thundercom	Pre_figure_turbox-c2130c-la1.1-qssi12	tianying.cheng@thundersoft.com

	m/apps/RemoteControlServer	-dev	
AF:RemoteControl: Service - Modify the connection rule1.Multiple devices are connected to the same screen at the same time, and the last connected device should have control of the screenTC-RID: 1201-0206001IssueID: TS-R-BUG-114912Change-Id: I8099b557bea7c8702f29488a189d9ef66fc06121			

#3 - 2023-01-03 19:45 - CD FW-程天颖

- Status changed from New to RESOLVED
- Assignee changed from CD FW-程天颖 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-01-03
- Root cause set to 当前的连接控制策略和需求不一致，按要求更改连接控制策略即可

■ Current conclusion

BUG已解决，提交已入库

■ My analysis

当前的连接控制策略和需求不一致，按要求更改连接控制策略即可

■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/vendor/thundercomm/apps/RemoteControlClients/+/173359>

<https://dev.thundercomm.com/gerrit/c/general/platform/vendor/thundercomm/apps/RemoteControlServer/+/173363>

#4 - 2023-01-04 10:53 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202301040309

1.4

验证通过

#5 - 2023-01-04 10:53 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files			
1653.jpg	73.4 KB	2022-12-28	CD TEST-方永红