

Figure - Bug #114957

【BSP】 【EVT2】 【FOTA】 V4.0交付版本, 不能使用模拟中控升级到V5.0

2022-12-30 10:36 - CDTS_TEST 刘勇

Status:	CLOSED	Start date:	2022-12-30
Priority:	Normal	Due date:	
Assignee:	CD BSP 叶鹏	% Done:	0%
Category:	BSP	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0054.X101
Need_Info:	--	Degrated:	--
Resolution:	--	Verified Version:	
Severity:	Major	Fixed Version:	
Reproducibility:	Every time	Root cause:	需求变更取消
Test Type:	IT		

Description
【前提条件】 1.中控环境搭建好 2.中控环境中有V5.0的update.zip全量包(FTP中文件名为：merged-qssi_figure-ota.zip) 【测试步骤】 1.中控通过网线链接路由，路由链接DUT通过wifi 2.中控IP：192.168.0.2， DUT-IP：192.168.0.18 3.进入终端，cd ~/server/目录，并运行命令 sudo ./run_https.sh sudo ./run_orch.sh adb shell logcat > logcat.txt 4.待功能启动 5.选择功能2（Download PACKAGE） 输入"2"->按"回车" ->输入 "1"->输入"update.zip" 6.等待下载完成并选择运行功能0（run script） 等待log中有提示下载完成(download succesful)-> 输入 "0"-> 按"回车"->等待升级成功（Need_Reboot） -> “ adb reboot ” 【期望结果】 6.升级成功 【实际结果】 6.升级失败,功能0运行不了 【备注】 V4.0版本：FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0054.X101 V5.0版本：FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0063.X101 使用DailyBuilde的1214user版本可以升级到V5.0版本， 手动*#149#升级可以从V4.0升级到V5.0

History

#1 - 2023-01-04 14:02 - CD BSP 叶鹏

博世FOTA接口取消

#2 - 2023-01-09 16:20 - CDTS_TEST 刘勇

- Category set to BSP

#3 - 2023-01-12 10:35 - CDTS-TEST 周婷

- Status changed from New to CLOSED
- Root cause set to 需求变更取消

博世fota接口取消，此问题暂时先处理处理

Files			
FAIL_logcat-054-063-full.txt	2.59 MB	2022-12-30	CDTS_TEST 刘勇