

Figure - Bug #114992

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT】【设置】搜索蓝牙耳机，图标显示为电脑的标识

2022-12-30 16:08 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-12-30
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0063.X
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Reproducibility:	Every time	Fixed Version:	2022-12-30
Test Type:	IT	Root cause:	UI 未适配。
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1、打开蓝牙			
2、附近有一个配对状态的蓝牙耳机			
【预期结果】			
2、设备搜索到蓝牙耳机，图标为耳机标识			
【实际结果】			
2、搜索到蓝牙耳机，图标显示为电脑的标识			

History

#1 - 2022-12-30 17:53 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
173462	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Adapter bluetooth device icon.TC-RID: 1201-0201801IssueID: TS-R-BUG-114992Change-Id: Id549240ef657fcf799f33e8f72ed9369d610084c			

#2 - 2022-12-30 17:58 - CD FW-廖涛

- Status changed from New to RESOLVED
- Assignee changed from CD FW-廖涛 to CD TEST- 方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2022-12-30
- Root cause set to UI 未适配。

■ Current conclusion

已处理。

■ My analysis

已适配蓝牙设备类型图标。

■ Next action

测试验证。

#3 - 2023-01-03 10:50 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202212310352

1.3

验证通过

#4 - 2023-01-03 10:50 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files

1603.png	245 KB	2022-12-30	CD TEST-方永红
----------	--------	------------	-------------