

Figure - Bug #114998

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 112101 (New): AF-V2.0-Launcher/SystemUI-控制中心

【AF】【EVT】【音乐播放器】音乐封面为白色时，无法看清楚播放器上面的按钮

2022-12-30 16:54 - CD TEST-方永红

Status:	CLOSED	Start date:	2022-12-30
Priority:	Normal	Due date:	2023-01-18
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0063.X
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Severity:	Normal	Fixed Version:	2023-01-17
Reproducibility:	Every time	Root cause:	音乐控制器样式适配问题导致。
Test Type:	IT		
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1、push一个音频到设备中			
2、进入音乐应用播放			
3、下划打开控制中心，观察音乐播放器显示			
【预期结果】			
3、可以清楚的看到播放器上面的暂停按钮			
【实际结果】			
3、无法看清楚播放器上面的按钮			

History

#1 - 2023-01-11 16:51 - CD FW 曹覃刚
- Due date set to 2023-01-18
- Status changed from New to ASSIGNED

UI图标是纯白色的，导致了这个问题，正在与UI同学讨论这个问题
大概率会制作新的图标替代，待UI同学回复或提供

#2 - 2023-01-12 14:14 - CD FW 曹覃刚
- Assignee changed from CD FW 曹覃刚 to CD FW-廖涛

#3 - 2023-01-17 18:35 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
177169	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com

#4 - 2023-01-17 18:37 - CD FW-廖涛

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW-廖涛 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-01-17
- Root cause set to 音乐控制器样式适配问题导致。

■ Current conclusion

已处理。

■ My analysis

音乐控制器样式适配问题导致，已按 UI 进行处理。

■ Next action

测试验证。

#5 - 2023-01-30 11:41 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202301300321

1.30

验证通过

#6 - 2023-01-30 11:41 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files			
1644.png	256 KB	2022-12-30	CD TEST-方永红
0001.mp3	432 KB	2022-12-30	CD TEST-方永红