

Figure - Bug #115026

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 112101 (New): AF-V2.0-Launcher/SystemUI-控制中心

【AF】【EVT】【控制中心】控制中心的亮度调节不能随设置中的调节实时变动

2023-01-03 18:12 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-01-03
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Severity:	Normal	Fixed Version:	2023-01-11
Reproducibility:	Every time	Root cause:	监听时机较晚，提前了监听时机
Test Type:	IT		
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1、打开设置-显示-亮度调节			
2、调节亮度			
3、下划打开控制中心			
4、观察亮度调节条			
【预期结果】			
4、亮度已经变为2中所调节的值			
【实际结果】			
4、亮度调节在打开控制中心之后才发生变化			

History

#1 - 2023-01-10 15:46 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
175497	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:QuickSettings: Fix the problem of delayed update of brightness barTC-RID: 1201-0201903IssueID: TS-R-BUG-115026Change-Id: I13bb7289ddc8457c44037ff5aed3b00b1992820b			

#2 - 2023-01-10 15:53 - CD FW 曹覃刚

- Status changed from New to RESOLVED
- Assignee changed from CD FW 曹覃刚 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No

- Fixed Version set to 2023-01-11
- Root cause set to 监听时机较晚，提前了监听时机

#3 - 2023-01-11 10:20 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202301110536

1.11

验证通过

#4 - 2023-01-11 10:21 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files			
Phone-STs40X190122 2023-01-03 18-03-11.mp4	16.8 MB	2023-01-03	CD TEST-方永红