

Figure - Bug #115106

【AF】【EVT2】【setting】【必现】设置内开关游戏模式，setting中切换后。控制中心不会同步变化。下拉后才会变化

2023-01-05 18:19 - SZTS_TEST 邹涛

Status:	CLOSED	Start date:	2023-01-05
Priority:	Normal	Due date:	
Assignee:	CD Test赵飞	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	[ro.build.display.id]: [01.00.X101_20221228_private_us
Need_Info:	--	Degraded:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-01-09
Reproducibility:	Every time	Root cause:	游戏模式状态变更后没有主动更新
Test Type:	Free Test		
Description			
前置条件： DUT处于开机状态			
操作步骤： 1.设置内反复打开/关闭，游戏模式 2.打开控制中心，查看游戏模式icon显示是否正确			
实际结果： 1、设置内开关游戏模式，setting中切换后。控制中心不会同步变化。下拉后才会变化			
预期结果： 1、设置内开关游戏模式，setting中切换后。控制中心同步变化			

History

#1 - 2023-01-05 18:55 - CD FW-廖涛

- Assignee changed from CD FW-廖涛 to CD FW 曹覃刚

#2 - 2023-01-06 17:46 - IoT scm

Gerrit Merge Information：			
ID	Project	Branch	Uploader
174628	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:GameMode: Fixed QuickSettings GameMode state update delayTC-RID: 1201-0204801IssueID: TS-R-BUG-115106Change-Id: I8a9319201f24850d995836dbdc86b653077ae8e1			

#3 - 2023-01-06 17:52 - CD FW 曹覃刚

- Status changed from New to RESOLVED

- Assignee changed from CD FW 曹覃刚到 SZTS_TEST 邹涛

- % Done changed from 0 to 100

- Resolution changed from -- to FIXED

- Degraded changed from -- to No

- Fixed Version set to 2023-01-09
- Root cause set to 游戏模式状态变更后没有主动更新

#4 - 2023-01-31 09:39 - CDTS_TEST 王成

- Assignee changed from SZTS_TEST 邹涛 to CD Test 赵飞

#5 - 2023-01-31 18:30 - CD Test 赵飞

- Status changed from RESOLVED to VERIFIED

验证版本：FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0070.X101

验证结果：PASS

#6 - 2023-01-31 18:30 - CD Test 赵飞

- Status changed from VERIFIED to CLOSED

Files

中科创达软件股份有限公司20230105-181423.mp4	1.06 MB	2023-01-05	SZTS_TEST 邹涛
---------------------------------	---------	------------	--------------