

Figure - Bug #115115

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT2】【添加微件】添加设置快捷方式的选项页面顶部显示为白色

2023-01-06 11:26 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-01-06
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0070.X
Reproducibility:	Every time	Fixed Version:	2023-01-09
Test Type:	ST	Root cause:	Settings UI 适配问题；
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1、长按桌面空白处进入桌面编辑模式			
2、点击添加微件			
3、选择设置快捷方式			
【预期结果】			
3、进入具体的快捷方式选择页面，页面显示合理			
【实际结果】			
3、添加设置快捷方式的选项页面顶部显示为白色			

History

- #1 - 2023-01-06 18:20 - CD APP-王营
- Status changed from New to ASSIGNED
- Assignee changed from CD APP-王营 to CD FW-廖涛

请检查一下这个页面的UI是否适配完成

com.android.settings/com.android.settings.Settings\$CreateShortcutActivity

- #2 - 2023-01-06 18:21 - CD APP-王营
- Category changed from CD-APP to CD-FW

#3 - 2023-01-09 17:37 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
175126	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com

#4 - 2023-01-09 17:38 - CD FW-廖涛

- Status changed from ASSIGNED to RESOLVED
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-01-09
- Root cause set to Settings UI 适配问题 ;

■ Current conclusion

已处理。

■ My analysis

添加微件界面未适配导致，已处理。

■ Next action

测试验证。

#5 - 2023-01-31 16:13 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Assignee changed from CD FW-廖涛 to CD TEST-方永红
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0070.X101

1.31

验证通过

#6 - 2023-01-31 16:13 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files			
1122222.png	65.9 KB	2023-01-06	CD TEST-方永红