

Figure - Bug #115129

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT】【设置】重复点击重置wlan按钮，页面一直闪烁

2023-01-06 16:01 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-01-06
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0067.X
Reproducibility:	Every time	Fixed Version:	2023-01-09
Test Type:	ST	Root cause:	progress dialog 显示隐藏过程太短，导致的视觉效果
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1、设置-系统-重置选项			
2、进入重置wlan选项			
3、重复点击重置wlan按钮			
【预期结果】			
3、每次都可以成功重置，且页面显示友好			
【实际结果】			
3、重复点击重置wlan按钮，页面一直闪烁			

History

- #1 - 2023-01-06 16:11 - CD FW-廖涛
- Assignee changed from CD FW-廖涛 to CD FW 曹覃刚
- #2 - 2023-01-06 16:12 - CD FW-廖涛
- Assignee changed from CD FW 曹覃刚 to CD FW-廖涛
- #3 - 2023-01-09 13:59 - CD FW-廖涛
- Status changed from New to RESOLVED
- Assignee changed from CD FW-廖涛 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-01-09
- Root cause set to progress dialog 显示隐藏过程太短，导致的视觉效果差。

■ Current conclusion

已处理。

■ My analysis

progress dialog 显示隐藏过程太短，导致的视觉效果差，已做优化处理。

■ Next action

测试验证。

#4 - 2023-01-10 11:19 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0067.X101

1.10
验证通过

#5 - 2023-01-10 11:19 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files

Phone-STS40X190122 2023-01-06 15-54-23.mp4	15.3 MB	2023-01-06	CD TEST-方永红
--	---------	------------	-------------