

Figure - Bug #115173

测试 Test-IT # 111062 (New): V3.0功能测试
测试 Test-IT # 111067 (New): AF-V3.0--Launcher/SystemUI-任务管理器

【AF】【EVT2】【任务管理器】打开应用小窗，关闭小窗，进recent，通过进程卡片右上角的按钮打开小窗，再次进recent，有明显的音乐进程卡片消失动画

2023-01-09 14:16 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-01-09
Priority:	Normal	Due date:	2023-01-13
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Need_Info:	--	Degrated:	--
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0068.X
Severity:	Normal	Fixed Version:	2023-01-12
Reproducibility:	Every time	Root cause:	小窗和进程同时存在，需要去掉一个。
Test Type:	IT		
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1、打开一应用小窗（以音乐为例）			
2、关闭小窗			
3、进recent，通过进程卡片右上角的按钮打开小窗			
4、再次进recent			
【预期结果】			
4、只有音乐的小窗卡片			
【实际结果】			
4、短时间内同时出现应用的小窗卡片和进程卡片，随后音乐进程卡片消失，有明显的消失动画			

History

- #1 - 2023-01-09 17:49 - CD APP-王营
 - Status changed from New to ASSIGNED
 - Assignee changed from CD APP-王营 to CD APP-王宏
- #2 - 2023-01-11 16:35 - CD APP-王营
 - Due date set to 2023-01-13
- #3 - 2023-01-12 16:41 - CD TEST-方永红
 - Subject changed from 【AF】【EVT2】【小窗模式】打开应用小窗，关闭小窗，进recent，通过进程卡片右上角的按钮打开小窗，再次进recent，有明显的音乐进程卡片消失动画 to 【AF】【EVT2】【任务管理器】打开应用小窗，关闭小窗，进recent，通过进程卡片右上角的按钮打开小窗，再次进recent，有明显的音乐进程卡片消失动画

#4 - 2023-01-12 19:50 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
175522	general/platform/packages/apps/Launcher3	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com

FW:Launcher:Fix recent display exception1.The page display is abnormal after the small window is switched to recentTC-RID: 1201-0205302IssueID: TS-R-DF-115173Change-Id: Ic679c41f4fe0ae1a1b82c7fb9b0087ec8ea1298d

#5 - 2023-01-12 19:56 - CD APP-王宏

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD APP-王宏 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Fixed Version set to 2023-01-12
- Root cause set to 小窗和进程同时存在，需要去掉一个。

■ My analysis

小窗和recent里的进程同时存在，需要去掉进程卡片，本次和小窗联合解决此问题

■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Launcher3/+175522>

注意：

这里等待 <http://10.0.232.3:3307/gerrit/c/general/platform/frameworks/base/+176074> 入库后，再开始测试

#6 - 2023-01-12 20:06 - IoT scm

Gerrit Merge Information：

ID	Project	Branch	Uploader
176074	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	lukf0916@thundersoft.com
AF:MultiWindow: fix tasks in recentsrevert commit eddbf42 and fix multi tasks in launcher part.TC-RID: 1201-0204601IssueID: TS-R-BUG-115173Change-Id: I1405edaa5a602359bab325bfd7af92f799ce603f			

#7 - 2023-01-13 15:40 - CD TEST-方永红

- File Phone-TZ98765432 2023-01-13 15-29-11.mp4 added
- Status changed from RESOLVED to VERIFY_FAILED
- Assignee changed from CD TEST-方永红 to CD APP-王宏
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0063.X101

1.13

无音乐进程卡片消失动效

但是空白卡片卡顿过于严重，需要优化

#8 - 2023-01-13 16:00 - CD APP-王宏

- Assignee changed from CD APP-王宏 to CD TEST-方永红

#9 - 2023-01-13 16:05 - CD TEST-方永红

- Status changed from VERIFY_FAILED to VERIFIED

1.13
卡顿问题另起票跟踪

#10 - 2023-01-13 16:05 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

#11 - 2023-01-13 16:06 - CD TEST-方永红
- Verified Version changed from FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0063.X101 to FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0068.X101

Files			
Phone-STS40X190122	2023-01-09 11-29-22.mp4	7.1 MB	2023-01-09
Phone-TZ98765432	2023-01-13 15-29-11.mp4	5.55 MB	2023-01-13