

Figure - Bug #115200

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】 【EVT2】 【设置】 连接蓝牙耳机，进入耳机设置详情页面，图标显示为电脑图标

2023-01-10 15:18 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-01-10
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0067.X
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0068.X
Severity:	Normal	Fixed Version:	2023-01-11
Reproducibility:	Every time	Root cause:	UI 适配问题
Test Type:	IT		
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1、连接一个蓝牙耳机			
2、进入耳机设置详情页面			
【预期结果】			
2、图标为耳机标识			
【实际结果】			
2、图标显示为电脑图标			

History

#1 - 2023-01-11 09:51 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
175704	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Fix bluetooth device icon in detail page.TC-RID: 1201-0201801IssueID: TS-R-BUG-115200Change-Id: I84dc79679f5c874ea1aba1f68ae6e34fe59f370f			

#2 - 2023-01-11 09:53 - CD FW-廖涛

- Status changed from New to RESOLVED
- Assignee changed from CD FW-廖涛 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-01-11
- Root cause set to UI 适配问题

■ Current conclusion

已处理。

■ My analysis

蓝牙设备详情图标未适配，已处理。

■ Next action

测试验证。

#3 - 2023-01-13 15:11 - CD TEST-方永红

- Status changed from *RESOLVED* to *VERIFIED*
- Verified Version set to *FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0068.X101*

1.13

验证通过

#4 - 2023-01-13 15:12 - CD TEST-方永红

- Status changed from *VERIFIED* to *CLOSED*

Files			
1456.png	218 KB	2023-01-10	CD TEST-方永红