

Figure - Bug #115202

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111051 (New): AF-V2.0-Launcher/SystemUI-通知中心

【AF】【EVT2】【通知中心】进入控制中心编辑页面，点击完成，通知中心的“前往通知设置”按钮单独出现

2023-01-10 15:31 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-01-10
Priority:	Normal	Due date:	2023-02-10
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0067.X
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Severity:	Normal	Fixed Version:	2023-01-18
Reproducibility:	Every time	Root cause:	原生现象，效果优化
Test Type:	ST		
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1、进入控制中心编辑页面			
2、点击完成			
【预期结果】			
2、由编辑组件页面切换到控制中心和通知中心			
【实际结果】			
2、在控制中心和通知中心整体出现后，“前往通知设置”按钮单独出现，体验性不好			

History

#1 - 2023-01-11 18:01 - CD FW 曹覃刚

- Due date set to 2023-02-10
- Status changed from New to ASSIGNED

#2 - 2023-01-17 13:38 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
177164	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Notification: Disable animation of aosp notification footerTC-RID: 1201-0201902IssueID: TS-R-BUG-115202Change-Id: la781f0c756e1115c3cfc50301b2f799f04f5a1bf			

#3 - 2023-01-17 13:39 - CD FW 曹覃刚

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW 曹覃刚到 CD TEST-方永红

- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-01-18
- Root cause set to 原生现象，效果优化

#4 - 2023-01-18 13:44 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202301180547

1.18
验证通过

#5 - 2023-01-18 13:45 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files			
Phone-STs40X190122 2023-01-10 15-06-40.mp4	9.42 MB	2023-01-10	CD TEST-方永红
1525.png	268 KB	2023-01-10	CD TEST-方永红