

Figure - Bug #115398

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111049 (New): AF-V2.0-副屏遥控器

【AF】【EVT】【遥控器】设置-屏保-系统屏保页面，无法用遥控器的上下左右进行选择

2023-01-18 16:19 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-01-18
Priority:	High	Due date:	2023-03-24
Assignee:	CD TEST-方永红	% Done:	100%
Category:	依赖UI/UE	Estimated time:	0.00 hour
Target version:	VC1_FSE_0086_20230328		
Need_Info:	--	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0069.X
Resolution:	FIXED	Degrated:	No
Severity:	Major	Verified Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C102(X102)
Reproducibility:	Every time	Fixed Version:	2023-03-31
Test Type:	ST	Root cause:	需求问题

Description	
【前提条件】	
1、设备已开机	
【测试步骤】	
1.设备连接遥控器	
2、进入设置-屏保-系统屏保页面	
3、在遥控器上进行上下左右的方向移动	
【预期结果】	
3、可以选中每个屏保的预览图	
【实际结果】	
3、无法用遥控器的上下左右进行选择	

History

- #1 - 2023-01-28 13:40 - CD APP-王营
- Status changed from New to NEED_INFO
 - Assignee changed from CD APP-王营 to CD TEST-方永红

请确认此需求，屏保应用没有适配遥控器按键，当前简单支持部分遥控器按键控制是原生控件的行为，但是原生控件并没有完美适配按键响应，如果增加这部分的适配会有很大的工作量，建议保持当前，只需适配手指触摸事件。

- #2 - 2023-01-30 14:49 - CD TEST-方永红
- Category changed from CD-APP to 依赖UI/UE
 - Assignee changed from CD TEST-方永红 to 方案组-RD3_CDTs 王浩云

哈喽，浩云
麻烦确认此处是否需要修改

- #3 - 2023-01-30 15:52 - 方案组-RD3_CDTs 王浩云

- Assignee changed from 方案组-RD3_CDTs 王浩云 to CD APP-王营

屏保需要对遥控器做一下适配

#4 - 2023-02-01 10:16 - CD APP-王营

- Assignee changed from CD APP-王营 to 方案组-RD3_CDTs 王浩云

Hi 浩云

遥控器适配需要额外开发，请帮忙确认开发排期。

#5 - 2023-02-03 13:48 - 方案组-RD3_CDTs 王浩云

- Due date set to 2023-03-15

- Target version set to VC1_FSE_0082_20230314

满足上下左右，确认/返回

#6 - 2023-02-03 13:55 - 方案组-RD3_CDTs 王浩云

- Assignee changed from 方案组-RD3_CDTs 王浩云 to CD APP-王营

#7 - 2023-03-02 09:24 - CD APP-王营

- Status changed from NEED_INFO to ASSIGNED

新增需求问题，优先解决紧急bug，这个问题先放后调整

#8 - 2023-03-13 17:55 - CD APP-王营

- Due date changed from 2023-03-15 to 2023-03-24

#9 - 2023-03-23 14:15 - CDTs_TEST 王成

- Target version changed from VC1_FSE_0082_20230314 to VC1_FSE_0086_20230328

需要确认两个点

- 1、只合入不测试？还是什么状态交付
- 2、是否包含中控的屏保

#10 - 2023-03-30 15:24 - CD APP-王营

- % Done changed from 0 to 50

- Resolution changed from -- to FIXED

- Degraded changed from -- to No

- Fixed Version set to 2023-03-31

- Root cause set to 需求问题

■ Current conclusion

开发完成

■ My analysis

需要添加遥控器按键处理以及焦点处理

■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/vendor/thundercomm/apps/ScreenSaver/+189900>

#11 - 2023-03-30 16:03 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
189900	general/platform/vendor/thundercomm/apps/ScreenSaver	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	ying.wang@thundersoft.com
AF: ScreenSaver: Adapt controllerTC-RID: 0301-0300601IssueID: TS-R-BUG-115398Change-Id: I9d8185a6f3df9b622fc36ddb9bf74e51dc6a1cd			

#12 - 2023-03-30 16:07 - CD APP-王营

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD APP-王营 to CD TEST-方永红
- % Done changed from 50 to 100

#13 - 2023-04-03 11:44 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_MCE_FSE.M.D.user.01.00.C102(X102).202304010020

4.1

目前屏保部分已经基本可以使用遥控器操作
其中《选中应用框在模拟app上按下ok键无反应》的问题已另起票跟踪
先关闭该Bug

#14 - 2023-04-03 11:44 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files			
1619.png	204 KB	2023-01-18	CD TEST-方永红