

Figure - Bug #115404

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111049 (New): AF-V2.0-副屏遥控器

【AF】 【EVT】 【遥控器】 首次购车激活页面，可以用遥控器打开屏保

2023-01-18 16:50 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-01-18
Priority:	High	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0069.X
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Severity:	Major	Fixed Version:	2023-01-30
Reproducibility:	Every time	Root cause:	没有限制激活应用的屏保开关 解决方案：在设
Test Type:	ST		
Description			
【前提条件】 1、设备处于首次购车激活页面			
【测试步骤】 1.设备已经连接遥控器 2、点击遥控器中的屏保按钮			
【预期结果】 2、无法进入屏保			
【实际结果】 2、可以进入屏保			

History

#1 - 2023-01-30 19:52 - CD FW-程天颖

- Status changed from New to RESOLVED

- Assignee changed from CD FW-程天颖 to CD TEST-方永红

- % Done changed from 0 to 100

- Resolution changed from -- to FIXED

- Degrated changed from -- to No

- Fixed Version set to 2023-01-30

- Root cause set to 没有限制激活应用的屏保开关

解决方案：在设置激活引导完成之前，禁止使用遥控器的屏保

■ Current conclusion

bug已解决，提交已入库

■ My analysis

没有限制激活应用的屏保开关

解决方案：在设置激活引导完成之前，禁止使用遥控器的屏保

■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/vendor/thundercomm/apps/RemoteControlServer/+/177714>

#2 - 2023-01-31 16:07 - CD TEST-方永红
- Status changed from *RESOLVED* to *VERIFIED*
- Verified Version set to *FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202301300321*

1.31
验证通过

#3 - 2023-01-31 16:07 - CD TEST-方永红
- Status changed from *VERIFIED* to *CLOSED*