

Figure - Bug #115414

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111054 (New): AF-V2.0-Launcher/SystemUI-控制中心-3游戏模式

【AF】【EVT】【游戏模式】OTA升级后，游戏模式图标位置异常

2023-01-18 18:47 - 物联网测试组_CDTs 段小刚

Status:	CLOSED	Start date:	2023-01-18
Priority:	Normal	Due date:	2023-02-03
Assignee:	物联网测试组_CDTs 段小刚	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	TEST	Found Version:	0068
Resolution:	FIXED	Degraded:	No
Severity:	Normal	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0071.X
Reproducibility:	Every time	Fixed Version:	2023-02-01
Test Type:	IT	Root cause:	记录的位置信息异常导致。

Description
【前提条件】 1、设备的游戏模式已打开 2、准备OTA升级包
【测试步骤】 1、进行OTA升级 2、打开游戏模式 3、打开 游戏
【预期结果】 3、游戏模式工具栏位置正常
【实际结果】 3、显示异常，位置在屏幕中间
【复现率】 3/3

History

#1 - 2023-01-30 14:22 - 物联网测试组_CDTs 段小刚
- File 游戏模式位置异常log.zip added

其复现过程中抓取的tlog已上传，请分析下问题

#2 - 2023-01-31 13:39 - CD FW 曹覃刚
- Due date set to 2023-02-03

#3 - 2023-02-01 09:57 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
178287	general/platform/vendor/thundercom m/apps/GameMode	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com

#4 - 2023-02-01 09:58 - CD FW-廖涛

- Status changed from New to RESOLVED
- Assignee changed from CD FW-廖涛 to 物联网测试组_CDTS 段小刚
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-02-01
- Root cause set to 记录的位置信息异常导致。

■ Current conclusion

已处理。

■ My analysis

记录的位置信息异常导致。

■ Next action

测试验证。

#5 - 2023-02-02 10:37 - 物联网测试组_CDTS 段小刚

- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0071.X101

验证版本：FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0071.X101

验证结果：从老版本OTA升级后，打开游戏其模式图标位置正常——Pass

#6 - 2023-02-02 10:39 - 物联网测试组_CDTS 段小刚

- Status changed from RESOLVED to VERIFIED

#7 - 2023-02-02 10:39 - 物联网测试组_CDTS 段小刚

- Status changed from VERIFIED to CLOSED

问题已解决，特此关闭

Files			
20230118-184504.jpg	564 KB	2023-01-18	物联网测试组_CDTS 段小刚
游戏模式位置异常log.zip	6.18 MB	2023-01-30	物联网测试组_CDTS 段小刚