Figure - Bug #115614

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT】【控制中心】编辑图标的尺寸不对

2023-01-31 17:49 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-01-31
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0070.3
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0071.)
Reproducibility:	Every time	Fixed Version:	2023-02-02
Test Type:	ST	Root cause:	调整UI
Description		•	

【前提条件】

1、设备已开机

【测试步骤】

- 1、打开控制中心
- 2、查看编辑图标尺寸

【预期结果】

2、内部编辑图标大小为32px*32px

【实际结果】

3、内部编辑图标大小远大于规定值

History

#1 - 2023-02-01 20:38 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader			
178622	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12	caoqg0702@thundersoft.com			
		-dev				
AF:QuickSettings: Modify edit button icon sizeTC-RID: 1201-0201903IssueID: TS-R-BUG-115614Change-Id: Iddf39a7f90a966c3d46c9ba4afa8af53cefd401c						

#2 - 2023-02-01 20:40 - CD FW 曹覃刚

- Status changed from New to RESOLVED
- Assignee changed from CD FW 曹覃刚 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-02-02
- Root cause set to 调整UI

#3 - 2023-02-02 10:52 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED

- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0071.X101

2.2 验证通过

#4 - 2023-02-02 10:52 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files

1749.png

124 KB

2023-01-31

CD TEST-方永红