

Figure - Bug #115665

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT】【通知中心】当通知中心内容多余一屏时，右侧没有滚动条

2023-02-01 14:22 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-02-01
Priority:	Normal	Due date:	2023-02-15
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0070.X
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Reproducibility:	Every time	Fixed Version:	2023-02-16
Test Type:	ST	Root cause:	需求变更

Description	
【前提条件】 1、设备已开机	
【测试步骤】 1、设备通知中心内容多余一屏	
【预期结果】 1、通知中心右侧应该有滚动条	
【实际结果】 1、通知中心右侧没有滚动条	

History

#1 - 2023-02-02 19:29 - CD FW 曹覃刚	
- Due date set to 2023-02-09	
- Status changed from New to ASSIGNED	
#2 - 2023-02-08 19:46 - CD FW 曹覃刚	
- Due date changed from 2023-02-09 to 2023-02-15	
影响小，优先解其他问题，变更计划完成日期	
#3 - 2023-02-10 09:40 - CD FW 曹覃刚	
- Assignee changed from CD FW 曹覃刚 to CD APP-王宏	
#4 - 2023-02-14 18:14 - CD APP-王宏	
- % Done changed from 0 to 50	
■ Current conclusion	
已提交	
■ My analysis	

根据滚动距离，可见控件高度和完整的内容高度来完成计算，进而绘制出scroll bar

■ Commit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/frameworks/base/+/181634>

#5 - 2023-02-15 13:40 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
181634	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com
AF:Notification:add scroll barTC-RID: 1201-0201902IssueID: TS-R-BUG-115665Change-Id: I9f7475c2bbbe8e6f061cab3a3a1fb5c3492fd6bf			

#6 - 2023-02-15 13:42 - CD APP-王宏

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD APP-王宏 to CD TEST-方永红
- % Done changed from 50 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-02-16
- Root cause set to 需求变更

#7 - 2023-02-15 20:39 - CD APP-王宏

- Status changed from RESOLVED to ASSIGNED
- Assignee changed from CD TEST-方永红 to CD APP-王宏

#8 - 2023-02-15 20:49 - CD APP-王宏

■ Current conclusion

已提交

■ My analysis

因为没有判断内容的高度和控件固定高度的大小，导致了异常情况，随补交此条commit

■ Commit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/frameworks/base/+/181980>

#9 - 2023-02-16 14:50 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
181980	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	hong.wang_a@thundersoft.com
AF:Notification:fixed scroll barTC-RID: 1201-0201902IssueID: TS-R-BUG-115665Change-Id: I72c97294a836488af9189b438218c5874efc8839			

#10 - 2023-02-16 19:45 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader

182289	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:Notification:Fix the problem that when the starting point is on the notification when scrolling up and down the notification center , sometimes it cannot be scrolled.TC-RID: 1201-0201902IssueID: TS-R-BUG-115665Change-Id: Ifce53b9550e7b2c50f402fea52c16dac985bbd5d			

#11 - 2023-02-16 19:46 - CD APP-王宏

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD APP-王宏 to CD TEST-方永红

#12 - 2023-02-20 10:35 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202302180012

2.20

验证通过

#13 - 2023-02-20 10:35 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files			
1421.png	523 KB	2023-02-01	CD TEST-方永红