

Figure - Bug #115712

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT】【通知中心】隐藏通知应用图标重叠方向有误

2023-02-01 17:24 - CD TEST-方永红

|                  |             |                   |                                                |
|------------------|-------------|-------------------|------------------------------------------------|
| Status:          | CLOSED      | Start date:       | 2023-02-01                                     |
| Priority:        | Normal      | Due date:         |                                                |
| Assignee:        | CD TEST-方永红 | % Done:           | 100%                                           |
| Category:        | CD-FW       | Estimated time:   | 0.00 hour                                      |
| Target version:  |             | Found Version:    | FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2 |
| Need_Info:       | --          | Degrated:         | No                                             |
| Resolution:      | FIXED       | Verified Version: | FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0071.X |
| Severity:        | Normal      | Fixed Version:    | 2023-02-02                                     |
| Reproducibility: | Every time  | Root cause:       | UI调整                                           |
| Test Type:       | ST          |                   |                                                |

|                             |  |
|-----------------------------|--|
| Description                 |  |
| 【前提条件】                      |  |
| 1、设备已开机                     |  |
| 【测试步骤】                      |  |
| 1、查看隐藏通知应用图标重叠情况            |  |
| 【预期结果】                      |  |
| 2、最左边的一个应用图标完整显示，后面的依次重叠一部分 |  |
| 【实际结果】                      |  |
| 2、最右边的一个应用图标完整显示            |  |

History

#1 - 2023-02-01 20:40 - IoT scm

Gerrit Merge Information :

| ID                                                                                                                                                                              | Project                          | Branch                                    | Uploader                  |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|-------------------------------------------|---------------------------|
| 178758                                                                                                                                                                          | general/platform/frameworks/base | Pre_figure_turbox-c2130c-la1.1-qssi12-dev | caoqg0702@thundersoft.com |
| AF:Notification: Change the stacking direction of the hidden notification iconsTC-RID: 1201-0201902IssueID: TS-R-BUG-115712Change-Id: lcc9aa4263b6d0a5e16dfe63249d52b373aa2d8f3 |                                  |                                           |                           |

#2 - 2023-02-01 20:43 - CD FW 曹覃刚

- Status changed from New to RESOLVED
- Assignee changed from CD FW 曹覃刚to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-02-02
- Root cause set to UI调整

#3 - 2023-02-02 10:54 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild\_HH\_VX1\_MCE\_FSE.M.R.user.01.00.0071.X101

2.2

验证通过

#4 - 2023-02-02 10:54 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

| Files    |        |            |             |
|----------|--------|------------|-------------|
| 1720.png | 131 KB | 2023-02-01 | CD TEST-方永红 |