

Figure - Bug #115770

【Figure】【EVT3】【RF】[WiFi RSSI]常温条件下，WiFi RSSI测试中，2.4 GWiFi 11g CH7 54M中存在Power Level偏高问题，标准值：-55 ± 3dBm，最高值：-50dBm，不符合企标。

2023-02-02 13:55 - SZ HW Test-曾小文

Status:	CLOSED	Start date:	2023-02-02
Priority:	High	Due date:	
Assignee:	SZ HW Test- 曾小文	% Done:	0%
Category:	EE	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	12月20号
Resolution:	--	Degrated:	--
Severity:	Major	Verified Version:	
Reproducibility:	Frequently	Fixed Version:	
Test Type:	Release Test	Root cause:	
Description			
[WiFi RSSI]常温条件下，WiFi RSSI测试中，2.4 GWiFi 11g CH7 54M中存在Power Level偏高问题，标准值：-55 ± 3dBm，最高值：-50dBm，不符合企标。			

History

#1 - 2023-02-02 14:18 - SZ HW Test- 曾小文

- Status changed from New to RESOLVED

这个板子前面测非信令Tx的时候，为了硬测能使用自动化工具，我通过改BDF把两个链路都开并导入到板子里。而测试RSSI的时候为信令模式，需要把CH1关闭，也就是把正式的BDF文件刷回去，否则RSSI会偏移，导致fail。

#2 - 2023-02-02 14:18 - SZ HW Test- 曾小文

- Status changed from RESOLVED to VERIFIED

复测PASS

#3 - 2023-02-02 14:18 - SZ HW Test- 曾小文

- Status changed from VERIFIED to CLOSED

- Assignee changed from 硬件二组_SD3 陈澍锴 to SZ HW Test- 曾小文