

Figure - Bug #115779

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT】【设置】显示页面各选项前没有配置相应的图标

2023-02-02 14:37 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-02-02
Priority:	Normal	Due date:	2023-02-06
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0071.X
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Reproducibility:	Every time	Fixed Version:	2023-02-03
Test Type:	ST	Root cause:	UI 适配遗漏。

Description	
【前提条件】	
1、设备已开机	
【测试步骤】	
1、查看设置-显示页面	
【预期结果】	
1、显示页面各选项前有相应的图标	
【实际结果】	
1、显示页面各选项前没有配置相应的图标	

History

#1 - 2023-02-02 19:31 - CD FW 曹覃刚

- Due date set to 2023-02-06

#2 - 2023-02-03 18:36 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
179255	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Add icons for display perference.TC-RID: 1201-0201813IssueID: TS-R-BUG-115779Change-Id: Ia8e0000d62f312cc5f03f84fcf06e637d00df7ee			

#3 - 2023-02-03 18:44 - CD FW-廖涛

- Status changed from New to RESOLVED

- Assignee changed from CD FW-廖涛 to CD TEST-方永红

- % Done changed from 0 to 100

- Resolution changed from -- to FIXED

- Degrated changed from -- to No

- Fixed Version set to 2023-02-03

- Root cause set to UI 适配遗漏。

■ Current conclusion

已处理，护眼模式选项图标 UI 未提供，所以没有。

■ My analysis

UI 适配遗漏。

■ Next action

测试验证。

#4 - 2023-02-06 16:42 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202302050304

2.6
除护眼模式外，其余图标已适配

#5 - 2023-02-06 16:43 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files			
1436.png	69.9 KB	2023-02-02	CD TEST-方永红