

Figure - Bug #115786

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT】【设置】部分页面的选项后方缺少箭头

2023-02-02 15:30 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-02-02
Priority:	Normal	Due date:	2023-02-09
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0071.X
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Reproducibility:	Every time	Fixed Version:	2023-02-07
Test Type:	ST	Root cause:	UI 适配遗漏。

Description	
【前提条件】	
1、设备已开机	
【测试步骤】	
1.查看设置内页面步骤	
【预期结果】	
1、页面显示与UI效果图一致	
【实际结果】	
1、部分页面的选项后方缺少箭头	

History

#1 - 2023-02-02 19:30 - CD FW 曹覃刚

- Due date set to 2023-02-09

#2 - 2023-02-07 16:43 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
179790	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:SettingsLib: Add right arrow icon for preference which could navigation.TC-RID: 1201-0201813IssueID: TS-R-BUG-115786Change-Id: lcc2902536fbc1b45bce688d1635fc2d14810c7b6			

#3 - 2023-02-07 16:43 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
179787	general/platform/packages/modules/Permission	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com

AF:Permission: Add right arrow icon for preference which could navigation.TC-RID: 1201-0201813IssueID: TS-R-BUG-115786Change-Id: lea1f33aa61737a94d398d22ffbdb5182822e712e

#4 - 2023-02-07 16:43 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
179791	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Add right arrow icon for preference which could navigation.TC-RID: 1201-0201813IssueID: TS-R-BUG-115786Change-Id: lbfd5bec09fb49349c582eae3ba42871a2c11b295			

#5 - 2023-02-07 16:45 - CD FW-廖涛

- Status changed from New to RESOLVED
- Assignee changed from CD FW-廖涛 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-02-07
- Root cause set to UI 适配遗漏。

■ Current conclusion

已处理。

■ My analysis

UI 适配遗漏，已完善。

■ Next action

测试验证。

#6 - 2023-02-07 17:57 - CD FW-廖涛

注意：由于【网络和互联网】以及【系统】-》【日期和时间】，这两个模块需要在后面裁剪掉，所以没有做处理。

#7 - 2023-02-08 11:06 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202302080731

2.8

验证通过

#8 - 2023-02-08 11:07 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

1523.png	186 KB	2023-02-02	CD TEST-方永红
----------	--------	------------	-------------