

Figure - Bug #115800

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT】【设置】应用-点进一个具体应用-通知，此时显示的应用图标后面有一个黑框

2023-02-02 16:34 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-02-02
Priority:	Normal	Due date:	2023-02-06
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0071.X
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Reproducibility:	Every time	Fixed Version:	2023-02-03
Test Type:	ST	Root cause:	原生样式未适配新 UI 导致。
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1.进入设置-应用页面			
2、随机点进一个最近使用过的应用			
3、点击通知			
4、查看页面显示			
【预期结果】			
4、页面显示一切正常			
【实际结果】			
4、应用图标后面有一个黑框			

History

#1 - 2023-02-02 19:30 - CD FW 曹覃刚

- Due date set to 2023-02-06

#2 - 2023-02-03 18:39 - CD FW-廖涛

- Status changed from New to RESOLVED

- Assignee changed from CD FW-廖涛 to CD TEST- 方永红

- % Done changed from 0 to 100

- Resolution changed from -- to FIXED

- Degrated changed from -- to No

- Fixed Version set to 2023-02-03

- Root cause set to 原生样式未适配新 UI 导致。

■ Current conclusion

已处理。

■ My analysis

原生样式未适配新 UI 导致。

■ Next action

测试验证。

#3 - 2023-02-06 16:36 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202302050304

2.6
验证通过

#4 - 2023-02-06 16:36 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

#5 - 2023-02-06 17:33 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
179603	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Remove app icon shadow in data usage detail page.TC-RID: 1201-0201813IssueID: TS-R-BUG-115800Change-Id: I7709559d756a077263b652324a1ee1a6dce81b02			

Files			
1622.png	147 KB	2023-02-02	CD TEST-方永红