Figure - Bug #115885 测试 Test-ST # 114575 (New): V5.0功能测试票 【AF】【EVT】【设置】屏保设置的UI界面中缺少对应一个图标

2023-02-04 13:54 - 物联网测试组_CDTS 段小刚

Status:	CLOSED	Start date:	2023-02-04
Priority:	Normal	Due date:	
Assignee:	物联网测试组_CDTS 段小刚	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	TEST	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0072.
Reproducibility:	Every time	Fixed Version:	2023-02-06
Test Type:	IT	Root cause:	UI适配遗漏。
【前提条件】 1、设备正常启动 【测试步骤】 1、打开设置——5 2、对比查看样式UI 【预期结果】 2、UI要与验收一致 【实际结果】 2、屏保设置页面缺	2示——屏保		
【复现率】 3/3			

History

#1 - 2023-02-06 17:33 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader			
179596	general/platform/packages/apps/Settin	Pre_figure_turbox-c2130c-la1.1-qssi12	tao.liao@thundersoft.com			
	gs	-dev				
AF:Settings: Add right icon for screen saver. TC-RID: 1201-0201813IssueID: TS-R-BUG-115885Change-Id: Idaefe93a933a14757138cd21ec73bfbf7a995ed5						

#2 - 2023-02-06 17:35 - CD FW-廖涛

- Status changed from New to RESOLVED
- Assignee changed from CD FW-廖涛 to 物联网测试组_CDTS 段小刚
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-02-06
- Root cause set to UI 适配遗漏。

Current conclusion 已处理。

My analysis UI 适配遗漏,已完善。

Next action 测试验证。

#3 - 2023-02-07 11:38 - 物联网测试组_CDTS 段小刚

- Status changed from RESOLVED to VERIFIED

- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0072.X101

验证版本:2月7号的版本 验证结果:其缺少的屏保设置UI已添加

#4 - 2023-02-07 11:38 - 物联网测试组_CDTS 段小刚

- Status changed from VERIFIED to CLOSED

Bug已修复,特此关闭

Files

20230204-134642.jpg

193 KB

2023-02-04

物联网测试组_CDTS 段小刚