

Figure - Bug #115921

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111049 (New): AF-V2.0-副屏遥控器

【AF】【EVT】【IOS-遥控器】遥控器应用列表页面，首次点击打开应用，第二次点击该应用无法关闭
2023-02-06 11:05 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-02-06
Priority:	High	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0073.X
Reproducibility:	Every time	Fixed Version:	2023-02-07
Test Type:	ST	Root cause:	未实现应用关闭功能。
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1.设备已经连接遥控器			
2、点击获取应用列表			
3、点击其中一个应用图标			
4、再次点击该应用图标			
【预期结果】			
4、关闭步骤三中的应用			
【实际结果】			
4、没有关闭步骤三中的应用			

History

#1 - 2023-02-07 14:11 - CD FW-廖涛
- Root cause set to 未实现应用关闭功能。

#2 - 2023-02-07 16:46 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
179892	general/platform/vendor/thundercom/apps/RemoteControlClients	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:RemoteControl: Client(iOS) - Support app stop function.TC-RID: 1201-0206003IssueID: TS-R-BUG-115921Change-Id: Idd49366b86640d2e16b69906c8243a2a0ad844f3			

#3 - 2023-02-07 16:47 - CD FW-廖涛
- Status changed from New to RESOLVED
- % Done changed from 0 to 100

- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-02-07

■ Current conclusion

已处理。

■ My analysis

未实现应用关闭功能，已处理。

■ Next action

测试验证。

#4 - 2023-02-07 16:48 - CD FW-廖涛

- Assignee changed from CD FW-廖涛 to CD TEST-方永红

#5 - 2023-02-09 10:42 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0073.X101

2.9

验证通过

#6 - 2023-02-09 10:42 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED