

Figure - Bug #115941

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】【EVT】【设置】设置-应用，部分页面左上角显示标题有误

2023-02-06 15:42 - CD TEST-方永红

|                      |             |                   |                                                |
|----------------------|-------------|-------------------|------------------------------------------------|
| Status:              | CLOSED      | Start date:       | 2023-02-06                                     |
| Priority:            | Normal      | Due date:         |                                                |
| Assignee:            | CD TEST-方永红 | % Done:           | 100%                                           |
| Category:            | CD-FW       | Estimated time:   | 0.00 hour                                      |
| Target version:      |             |                   |                                                |
| Need_Info:           | --          | Found Version:    | FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2 |
| Resolution:          | FIXED       | Degrated:         | No                                             |
| Severity:            | Normal      | Verified Version: | FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0073.X |
| Reproducibility:     | Every time  | Fixed Version:    | 2023-02-08                                     |
| Test Type:           | ST          | Root cause:       | 页面跳转未设置标题导致。                                   |
| Description          |             |                   |                                                |
| 【前提条件】               |             |                   |                                                |
| 1、设备已开机              |             |                   |                                                |
| 【测试步骤】               |             |                   |                                                |
| 1、设置-应用              |             |                   |                                                |
| 2、点击一个具体应用           |             |                   |                                                |
| 3、遍历应用下方的选项列表        |             |                   |                                                |
| 【预期结果】               |             |                   |                                                |
| 3、每个页面左上角的标题与该页面名称一致 |             |                   |                                                |
| 【实际结果】               |             |                   |                                                |
| 3、部分页面左上角显示标题有误      |             |                   |                                                |

History

#1 - 2023-02-08 15:17 - IoT scm

Gerrit Merge Information :

| ID                                                                                                                                                       | Project                                     | Branch                                        | Uploader                 |
|----------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------|-----------------------------------------------|--------------------------|
| 180094                                                                                                                                                   | general/platform/packages/apps/Settin<br>gs | Pre_figure_turbox-c2130c-la1.1-qssi12<br>-dev | tao.liao@thundersoft.com |
| AF:Settings: Fix title error in application detail page.TC-RID: 1201-0201813IssueID: TS-R-BUG-115941Change-Id: I222352c92b03e59fc1161b267f9986f781d56c40 |                                             |                                               |                          |

#2 - 2023-02-08 15:18 - CD FW-廖涛

- Status changed from New to RESOLVED
- Assignee changed from CD FW-廖涛 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-02-08

- Root cause set to 页面跳转未设置标题导致。

■ Current conclusion

已处理，代码已入库。

■ My analysis

页面跳转未设置标题导致。

■ Next action

测试验证。

#3 - 2023-02-09 11:20 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED

- Verified Version set to FlatBuild\_HH\_VX1\_MCE\_FSE.M.R.user.01.00.0073.X101

2.9

验证通过

#4 - 2023-02-09 11:20 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

| Files     |        |            |             |
|-----------|--------|------------|-------------|
| 1529.png  | 176 KB | 2023-02-06 | CD TEST-方永红 |
| 1530.png  | 158 KB | 2023-02-06 | CD TEST-方永红 |
| 15302.png | 166 KB | 2023-02-06 | CD TEST-方永红 |
| 15303.png | 187 KB | 2023-02-06 | CD TEST-方永红 |