

Figure - Bug #115987

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】 【EVT】 【设置】 设置-应用-设置-流量统计页面， 设置图标显示有误

2023-02-07 14:57 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-02-07
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0072.X
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0074.X
Severity:	Normal	Fixed Version:	2023-02-13
Reproducibility:	Every time	Root cause:	Settings UI 适配遗漏。
Test Type:	ST		
Description			
【前提条件】 1、设备已开机			
【测试步骤】 1、查看设置-应用-设置-流量统计页面			
【预期结果】 1、页面内的图标为设置图标			
【实际结果】 1、设置图标显示有误			

History

#1 - 2023-02-07 17:04 - CD FW-廖涛

- Status changed from New to RESOLVED
- Assignee changed from CD FW-廖涛 to CD TEST-方永红
- Resolution changed from -- to WONTFIX
- Root cause set to AOSP 设计如此， 设置的流量统计就是统计的 Android 操作系统的。

■ Current conclusion

无需处理。

■ My analysis

AOSP 设计如此， 设置的流量统计就是统计的 Android 操作系统的。

■ Next action

测试跟进。

#2 - 2023-02-07 17:07 - CD TEST-方永红

- Status changed from RESOLVED to ASSIGNED
- Assignee changed from CD TEST-方永红 to CD FW-廖涛

2.7

图标为原生样式，暂不做修改，仅修改图标下方下拉框内容显示不清晰问题

#3 - 2023-02-13 20:30 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
181364	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Fix spinner style problem.1. Modify spinner style problem;2. Add spinner drop down view style with radio button;TC-RID: 1201-0201813IssueID: TS-R-BUG-115987Change-Id: I8dfb8b28e3e96be62b5ed19373eea509d1c6a771			

#4 - 2023-02-13 20:30 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
181465	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Add onPopupWindowDismissCallback to Spinner.TC-RID: 1201-0201813IssueID: TS-R-BUG-115987Change-Id: I5fecb4a2f6a676ad9bfca59b390dcbc3be0cd279			

#5 - 2023-02-13 20:31 - CD FW-廖涛

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW-廖涛 to CD TEST-方永红
- % Done changed from 0 to 100
- Resolution changed from WONTFIX to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-02-13
- Root cause changed from AOSP 设计如此， 设置的流量统计就是统计的 Android 操作系统的。 to Settings UI 适配遗漏。

■ Current conclusion

已处理，代码已入库。

■ My analysis

Settings UI 适配遗漏。

■ Next action

测试验证。

#6 - 2023-02-14 18:36 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0074.X101

2.14
验证通过

#7 - 2023-02-14 18:36 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

Files			
1451.png	179 KB	2023-02-07	CD TEST-方永红