

Figure - Bug #116078

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】 【EVT2】 【蓝牙】 与蓝牙设备连接成功后，没有toast提示

2023-02-08 15:28 - CD Test赵飞

Status:	CLOSED	Start date:	2023-02-08
Priority:	Normal	Due date:	2023-02-10
Assignee:	CD Test赵飞	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-02-13
Reproducibility:	Every time	Root cause:	连接成功没有弹出toast
Test Type:	ST		
Description			
【前提条件】 1、设备已开机 2、准备一个蓝牙耳机			
【测试步骤】 1、进入设置- 已连接的设备 - 与新设备配对 2、点击搜索到的蓝牙设备名称进行配对连接			
【预期结果】 2、配对连接成功后，页面弹出toast “ xxx ” 的耳机连接成功			
【实际结果】 2、配对连接成功后没有弹出toast			
【日志】 截图见附件			
【备注】 断开连接后，重新连接成功后，也没有toast提示			
Related issues:			
Related to Figure - Bug # 116081: 【AF】 【EVT2】 【蓝牙】 与蓝牙设备连接失败...		CLOSED	2023-02-08 2023-02-20

History

- #1 - 2023-02-08 15:30 - CD Test赵飞
- Description updated
- #2 - 2023-02-08 17:14 - CD FW 曹覃刚
- Status changed from New to ASSIGNED
- Assignee changed from CD FW 曹覃刚 to CD FW-程天颖
- #3 - 2023-02-08 20:03 - CD FW 曹覃刚
- Due date set to 2023-02-10
- #4 - 2023-02-13 17:27 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
181081	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:Settings: Fix have no Toast pop when connect bluetooth successTC-RID: 1201-0201801IssueID: TS-R-BUG-116078Change-Id: I775f31bfc9b0b1e3dbbceb08ecbdf0f75d380967			

#5 - 2023-02-13 17:31 - CD FW-程天颖

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW-程天颖 to CD Test赵飞
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-02-13
- Root cause set to 连接成功没有弹出toast

■ Current conclusion

代码已入库

■ My analysis

连接成功没有弹出toast

■ Submit Url

<https://dev.thundercomm.com/gerrit/c/general/platform/frameworks/base/+ /181081>

#6 - 2023-02-14 11:57 - CD Test赵飞

- Status changed from RESOLVED to VERIFIED

验证版本：FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202302100501

验证结果：PASS

多次弹出toast的问题在Bug #116081中修改

#7 - 2023-02-14 11:57 - CD Test赵飞

- Status changed from VERIFIED to CLOSED

Files

screen-20230208-102655.mp4	5.18 MB	2023-02-08	CD Test赵飞
0_17_Setting_1_3_蓝牙_配对成功.png	766 KB	2023-02-08	CD Test赵飞