

Figure - Bug #116096

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT2】【蓝牙】进入“与新设备配对”页面时，页面闪现“未在附近找到蓝牙设备。”的文言
2023-02-08 17:42 - CD Test赵飞

Status:	CLOSED	Start date:	2023-02-08
Priority:	Normal	Due date:	2023-02-10
Assignee:	CD Test赵飞	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-02-11
Reproducibility:	Every time	Root cause:	ProgressCategory在初始化时设置了hodler为空的提示
Test Type:	ST		
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1、进入设置- 已连接的设备 - 与新设备配对			
【预期结果】			
1、页面显示正常			
【实际结果】			
1、页面闪现“未在附近找到蓝牙设备。”的文言			
【日志】			
截图见附件			

History

#1 - 2023-02-08 19:56 - CD FW 曹覃刚
- Due date set to 2023-02-10
- Assignee changed from CD FW 曹覃刚 to CD FW-程天颖

设置页面闪现“未在附近找到蓝牙设备。”的文言
检查显示条件，根据UE/UI，可以考虑删除这个提示

#2 - 2023-02-11 14:18 - CD FW-程天颖
- Root cause set to ProgressCategory在初始化时设置了hodler为空的提示文本，刚进入添加蓝牙页面时，蓝牙列表会为空，所以有提示文本

如果不设置提示文本会导致空指针异常，所以把提示文本设置为空白，提示文本也不再弹出

■ Current conclusion
代码已提交
■ My analysis

ProgressCategory在初始化时设置了hodler为空的提示文本，刚进入添加蓝牙页面时，蓝牙列表会为空，所以有提示文本
如果不设置提示文本会导致空指针异常，所以把提示文本设置为空白，提示文本也不再弹出

■ Next action

代码入库

#3 - 2023-02-11 15:56 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
181039	general/platform/packages/apps/Settins	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tianying.cheng@thundersoft.com
AF:Settings: Fix flashes text when paired with BluetoothTC-RID: 1201-0201801IssueID: TS-R-BUG-116096Change-Id: I9151f7fcec8f1c54acaf30bec57815733730056			

#4 - 2023-02-11 15:59 - CD FW-程天颖

- Status changed from New to RESOLVED
- Assignee changed from CD FW-程天颖 to CD Test赵 飞
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-02-11

■ Current conclusion

代码已提交

■ My analysis

ProgressCategory在初始化时设置了hodler为空的提示文本，刚进入添加蓝牙页面时，蓝牙列表会为空，所以有提示文本
如果不设置提示文本会导致空指针异常，所以把提示文本设置为空白，提示文本也不再弹出

■ Submit Url

<https://dev.thundercomm.com/gerrit/c/general/platform/packages/apps/Settings/+181039>

#5 - 2023-02-14 10:45 - CD Test赵 飞

- Status changed from RESOLVED to VERIFIED

验证版本：FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0074.X101

验证结果：PASS

#6 - 2023-02-14 10:45 - CD Test赵 飞

- Status changed from VERIFIED to CLOSED

Files

screenshot.png	409 KB	2023-02-08	CD Test赵 飞
screen-20230208-070812.mp4	2.01 MB	2023-02-08	CD Test赵 飞