

Figure - Bug #116125

测试 Test-ST # 114575 (New): V5.0功能测试票

测试 Test-ST # 114577 (New): Launcher/SystemUI

【AF】 【EVT2】 【蓝牙】 搜索到蓝牙音箱图标显示为电脑图标

2023-02-09 16:10 - CD Test赵飞

Status:	CLOSED	Start date:	2023-02-09
Priority:	Normal	Due date:	2023-02-10
Assignee:	CD Test赵飞	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0073.X
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-02-10
Reproducibility:	Every time	Root cause:	更改默认图标为指向性不强的蓝牙图标
Test Type:	ST		

Description
【前提条件】 1、设备已开机 2、准备一个蓝牙音箱
【测试步骤】 1、进入设置 - 已连接设备 - 与新设备配对 2、查看搜索到的蓝牙音箱图标显示
【预期结果】 2、蓝牙音箱图标显示正确
【实际结果】 2、蓝牙音箱图标显示为电脑图标
【日志】 截图见附件

History

#1 - 2023-02-09 16:54 - CD FW 曹覃刚

- Due date set to 2023-02-10

- Status changed from New to ASSIGNED

■ 当前的状态

当前只有四种设备提供了切图

耳机，鼠标，键盘手柄

其他设备均使用默认的切图

■ 分析过程

默认切图形似电脑，指向性太明显

与需求浩云以及UI同学确认，要替换当前的默认切图

■ 下一步

待UI同学提供切图后替换

#2 - 2023-02-09 19:59 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
180684	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	caoqg0702@thundersoft.com
AF:Settings: Change the icon of the default Bluetooth device.TC-RID: 1201-0201801IssueID: TS-R-BUG-116125Change-Id: Ibb1ecee563de74e1b14788b9bc06f52f299d57b7			

#3 - 2023-02-09 20:00 - CD FW 曹覃刚

- Status changed from ASSIGNED to RESOLVED
- Assignee changed from CD FW 曹覃刚 to CD Test赵飞
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-02-10
- Root cause set to 更改默认图标为指向性不强的蓝牙图标

#4 - 2023-02-10 17:12 - CD Test赵飞

- Status changed from RESOLVED to VERIFIED

验证版本：FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202302100501

验证结果：PASS

#5 - 2023-02-10 17:12 - CD Test赵飞

- Status changed from VERIFIED to CLOSED

Files

Screenshot_20230209-042504.png	516 KB	2023-02-09	CD Test赵飞
--------------------------------	--------	------------	-----------