

Figure - Bug #116264

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT】【设置】点击设置中的应用，选择任意应用，选择卸载，写在完成后未返回上一级界面，且再次点击卸载后，闪退回桌面

2023-02-15 17:25 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-02-15
Priority:	High	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:	VC1_FSE_0078_20230228	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Severity:	Major	Fixed Version:	2023-02-17
Reproducibility:	Every time	Root cause:	应用卸载后置操作逻辑适配两栏展示问题导致。
Test Type:	ST		
Description			
【前提条件】			
1、设备正常启动			
【测试步骤】			
1.进入设置			
2.点击应用			
3.点击查看更多应用			
4.选择任意应用			
5进入详情后点击卸载			
6.操作完成卸载后再次点击卸载			
【预期结果】			
6、卸载完成后可以返回上一级界面并且可继续操作			
【实际结果】			
6、卸载完成后未返回上一级界面，且再次点击卸载直接闪退至桌面			
【复现率】			
3/3			

History

#1 - 2023-02-17 10:26 - CD TPM-王祥林

- Target version set to VC1_FSE_0078_20230228

#2 - 2023-02-17 19:00 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
182427	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:PackageInstaller: Adapter dialog style.TC-RID: 1201-0201813IssueID: TS-R-BUG-116264Change-Id: I58074f0f3fb24f01a7cb10aed6b9996456325868			

#3 - 2023-02-17 19:00 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
182426	general/platform/packages/apps/Settin gs	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	tao.liao@thundersoft.com
AF:Settings: Fix settings has been killed when uninstall app.TC-RID: 1201-0201802IssueID: TS-R-BUG-116264Change-Id: I6c0e8ac36ca3c762d5b5ae9df985baf2f9ae665d			

#4 - 2023-02-17 19:16 - CD FW-廖涛

- Status changed from New to RESOLVED
- Assignee changed from CD FW-廖涛 to CD TEST- 方永红
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-02-17
- Root cause set to 应用卸载后置操作逻辑适配两栏展示问题导致。

■ Current conclusion

已处理，代码已入库。

■ My analysis

应用卸载后置操作逻辑适配两栏展示问题导致。已处理为返回上一页，如果当前已经是第一页（从外部跳转到应用详情），则退出 Settings。

■ Next action

测试验证。

#5 - 2023-02-20 10:45 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.202302180012

2.20

验证通过

#6 - 2023-02-20 10:45 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files

Phone-STs40X190078 2023-02-15 17-25-04.mp4	24.9 MB	2023-02-15	CD TEST-方永红
--	---------	------------	-------------