

Figure - Bug #116335

测试 Test-IT # 110961 (New): V2.0功能测试

测试 Test-IT # 112101 (New): AF-V2.0-Launcher/SystemUI-控制中心

【AF】【EVT3】【控制中心】控制中心编辑页面，点击再长按页面上的备选控件后，备选控件右上角的“+”置灰

2023-02-17 14:31 - CD Test赵飞

Status:	CLOSED	Start date:	2023-02-17
Priority:	Normal	Due date:	
Assignee:	CD Test赵飞	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Need_Info:	--	Degrated:	No
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-02-20
Reproducibility:	Every time	Root cause:	连续点击释放会造成Enable状态出现问题，当每次
Test Type:	ST		
Description			
【前提条件】			
1、设备已开机			
【测试步骤】			
1、下划打开控制中心			
2、点击屏幕右上角的编辑按钮			
3、点击备选控件列表中的任意一个控件，如“闹钟”			
4、点击后再长按“闹钟”			
5、查看			
【预期结果】			
5、控件显示正常，可以正常添加备选控件至“使用中”区域			
【实际结果】			
5、两个备选控件右上角的“+”都置灰了，无法添加至“使用中”区域			
【日志】			
见附件			

History

#1 - 2023-02-17 18:05 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
182616	general/platform/frameworks/base	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	caoqg0702@thundersoft.com
AF:QuickSettings:Update enable status when the item is refactoredTC-RID: 0301-0201903IssueID: TS-R-BUG-116335Change-Id: I785a3e3d79a3f534b8c61c1cdb17318cf29dd1a1			

#2 - 2023-02-17 18:07 - CD FW 曹覃刚

- Status changed from New to RESOLVED
- Assignee changed from CD FW 曹覃刚 to CD Test赵飞
- % Done changed from 0 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-02-20
- Root cause set to 连续点击释放会造成Enable状态出现问题，当每次重构view时，更新此状态

#3 - 2023-02-21 14:14 - CD Test赵飞

- Status changed from RESOLVED to VERIFIED

验证版本：FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0076.X101
验证结果：PASS

#4 - 2023-02-21 14:14 - CD Test赵飞

- Status changed from VERIFIED to CLOSED

Files			
screen-20230217-081542.mp4	2.74 MB	2023-02-17	CD Test赵飞
logcat.txt	2.25 MB	2023-02-17	CD Test赵飞