

Figure - Bug #116374

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111050 (New): AF-V2.0-Launcher/SystemUI-桌面管理

【AF】【EVT】【桌面】长按应用图标点击“应用信息”，桌面短暂闪烁后才进入相应的“应用信息”页面
2023-02-20 11:37 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-02-20
Priority:	Normal	Due date:	2023-03-03
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:			
Need_Info:	--	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101.202303
Reproducibility:	Every time	Fixed Version:	2023-03-03
Test Type:	ST	Root cause:	与116460相同 由于页面实际经过两次切换，造
Description			
【前提条件】			
1、设备正常启动			
【测试步骤】			
1、长按应用图标点击“应用信息”			
【预期结果】			
1、直接进入相应的“应用信息”页面			
【实际结果】			
1、桌面短暂闪烁后才进入相应的“应用信息”页面			
【复现率】			
3/3			

History
#1 - 2023-02-27 10:59 - CD APP-王营
- Status changed from New to ASSIGNED
- Assignee changed from CD APP-王营 to CD FW-廖涛
to 廖涛
请帮忙看一下打开setting界面的页面展开逻辑
#2 - 2023-02-28 10:44 - CD FW-廖涛
- Due date set to 2023-03-03
#3 - 2023-03-01 18:50 - CD FW-廖涛
- Assignee changed from CD FW-廖涛 to CD FW 曹覃刚
#4 - 2023-03-02 15:19 - CD FW 曹覃刚
- Category changed from CD-APP to CD-FW

- Status changed from ASSIGNED to RESOLVED
 - Assignee changed from CD FW 曹覃刚 to CD TEST-方永红
 - % Done changed from 0 to 100
 - Resolution changed from -- to FIXED
 - Degrated changed from -- to No
 - Fixed Version set to 2023-03-03
 - Root cause set to 与116460相同
- 由于页面实际经过两次切换，造成了这个问题。改为了一次切换

- #5 - 2023-03-03 14:45 - CD TEST-方永红
- Status changed from RESOLVED to VERIFIED
 - Verified Version set to FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101.202303030144

3.3

验证通过

- #6 - 2023-03-03 14:46 - CD TEST-方永红
- Status changed from VERIFIED to CLOSED

Files			
Phone-ST540X190078 2023-02-20 11-37-04.mp4	11.6 MB	2023-02-20	CD TEST-方永红