

Figure - Bug #116387

测试 Test-IT # 110867 (New): V1.0测试功能汇总

测试 Test-IT # 110895 (New): AF-V1.0功能测试-桌面

【AF】【EVT3】【时钟】创建两个定时器等超时后，从通知中心进入定时器，定时器显示界面异常并且后台出现两个进程

2023-02-20 16:24 - CDTs\_Test 吴诗雨

Status:	CLOSED	Start date:	2023-02-20
Priority:	High	Due date:	2023-03-15
Assignee:	CDTS_Test 吴诗雨	% Done:	0%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Need_Info:	--	Degrated:	--
Resolution:	FIXED	Verified Version:	
Severity:	Major	Fixed Version:	
Reproducibility:	Every time	Root cause:	需求变更
Test Type:	ST		
Description			
<p>【前提条件】</p> <p>1、设备已开机</p> <p>【测试步骤】</p> <p>1、创建两个定时器并等待其超时</p> <p>2、下划打开通知中心</p> <p>3、点击定时器通知，观察界面</p> <p>4、返回主页，上划进入recent界面，观察进程</p> <p>【预期结果】</p> <p>3、定时器显示界面正常</p> <p>4、只有一个定时器进程</p> <p>【实际结果】</p> <p>3、定时器显示界面出现一大一小显示</p> <p>4、有两个定时器进程</p> <p>【日志】</p> <p>见附件</p>			

History

- #1 - 2023-02-24 10:42 - CD APP-王营
- Due date set to 2023-03-15

- Status changed from New to ASSIGNED

- Assignee changed from CD APP-王营 to CD APP-王宏
- #2 - 2023-02-24 15:51 - CD APP-王宏
- Status changed from ASSIGNED to NEED\_INFO

- Assignee changed from CD APP-王宏 to CDTs\_Test 吴诗雨

- Resolution changed from -- to FIXED

- Root cause set to 需求变更

Current conclusion  
问题已经解决

My analysis  
根据最新的需求,时钟app被删除

Submit URL  
[https://dev.thundercomm.com/gerrit/c/general/platform/vendor/thundercomm/apps/app\\_rm/+/184138](https://dev.thundercomm.com/gerrit/c/general/platform/vendor/thundercomm/apps/app_rm/+/184138)

#3 - 2023-02-24 16:09 - CDTS\_Test 吴诗雨  
- Status changed from NEED\_INFO to RESOLVED

#4 - 2023-02-24 16:09 - CDTS\_Test 吴诗雨  
- Status changed from RESOLVED to VERIFIED

根据最新的需求,时钟app被删除，故关闭bug

#5 - 2023-02-24 16:09 - CDTS\_Test 吴诗雨  
- Status changed from VERIFIED to CLOSED

Files			
20230220-161251.mp4	7.9 MB	2023-02-20	CDTS_Test 吴诗雨