

Figure - Bug #116388

测试 Test-IT # 110867 (New): V1.0测试功能汇总

测试 Test-IT # 110895 (New): AF-V1.0功能测试-桌面

【AF】【EVT3】【时钟】创建三个定时器等待超时后，从通知中心进入定时器，定时器只显示两个并且偶现crash

2023-02-20 17:01 - CDTs_Test 吴诗雨

Status:	CLOSED	Start date:	2023-02-20
Priority:	Urgent	Due date:	2023-03-15
Assignee:	CDTS_Test 吴诗雨	% Done:	0%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Need_Info:	--	Degrated:	--
Resolution:	FIXED	Verified Version:	
Severity:	Major	Fixed Version:	
Reproducibility:	Every time	Root cause:	需求变更
Test Type:	ST		

Description
【前提条件】 1、设备已开机
【测试步骤】 1、创建三个定时器并等待其超时 2、下划打开通知中心 3、从通知中心进入定时器，观察界面 4、多次从通知中心进入定时器
【预期结果】 3、显示三个定时器 4、正常进入定时器界面
【实际结果】 3、只显示两个定时器 4、偶现crash的情况
【日志】 见附件

History

#1 - 2023-02-20 17:19 - CDTs_Test 吴诗雨

- File 20230220-171333.mp4 added

除crash外还会出现，点击通知中心的定时器无法正常打开的情况

步骤：

- 1、创建三个定时器，两个超时一个不超时
- 2、返回主页，下划打开通知中心
- 3、点击不超时的定时器
- 4、再次打开通知中心，点击超时的定时器
- 5、重复3、4两个操作

现象：

- 1、无法打开定时器，仍停留在主页
- 2、出现crash的情况

#2 - 2023-02-24 10:42 - CD APP-王营

- Due date set to 2023-03-15
- Status changed from New to ASSIGNED
- Assignee changed from CD APP-王营 to CD APP-王宏

#3 - 2023-02-24 15:52 - CD APP-王宏

- Status changed from ASSIGNED to RESOLVED
- Resolution changed from -- to FIXED
- Root cause set to 需求变更

■ Current conclusion

问题已经解决

■ My analysis

根据最新的需求,时钟app被删除

■ Submit URL

https://dev.thundercomm.com/gerrit/c/general/platform/vendor/thundercomm/apps/app_rm/+184138

#4 - 2023-02-24 15:53 - CD APP-王宏

- Assignee changed from CD APP-王宏 to CDTS_Test 吴诗雨

#5 - 2023-02-24 16:05 - CDTS_Test 吴诗雨

- Status changed from RESOLVED to VERIFIED

根据最新的需求,时钟app被删除,故关闭bug

#6 - 2023-02-24 16:05 - CDTS_Test 吴诗雨

- Status changed from VERIFIED to CLOSED

Files			
20230220-164806.jpeg	116 KB	2023-02-20	CDTS_Test 吴诗雨
logcat.txt	19.7 MB	2023-02-20	CDTS_Test 吴诗雨
20230220-171333.mp4	13.2 MB	2023-02-20	CDTS_Test 吴诗雨