

Status:	CLOSED	Start date:	2023-02-22
Priority:	Normal	Due date:	
Assignee:	CDTS_Test 吴诗雨	% Done:	100%
Category:	BSP	Estimated time:	0.00 hour
Target version:		Found Version:	userdebug 0068- userdebug 0075
Need_Info:	TEST	Degrated:	--
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	
Reproducibility:	Occasionally	Root cause:	背光亮度值为 0 时，背光并未完全关闭
Test Type:	ST		
Description			
【前提条件】 None			
【测试步骤】 1. 烧写最新MCU mot 0.0.9 2. 然后烧0068的版本，这个mcu是 0.0.7 这里会生一次降级MCU降级，在降级过程中断电 3. 再烧0075的版本，MCU 0.0.9，这里会生一次降级MCU降级，在降级过程中断电 4. 最后循环升降			
【预期结果】 每次均能正常启动			
【实际结果】 循环第十三次后，设备反复进行进入recovery 初步分析为key 未备份			

History

- #1 - 2023-02-28 13:49 - CD TPM-王祥林
- Category set to BSP
- #2 - 2023-03-02 10:29 - CD BSP-杜磊
- Status changed from New to RESOLVED
- Assignee changed from CD BSP- 杜磊 to 移动测试一组_CDTS 刘强
- Need_Info changed from -- to TEST
- Resolution changed from -- to FIXED
- Root cause set to 背光亮度值为 0 时，背光并未完全关闭

Hi, 刘强，

帮忙验证一下VB版本：

http://cdiot@192.168.87.46/Pre_figure/VerifyBuild/Pre_figure_turbox-c2130c-la1.1-qssi12-dev/20230301/202303012056-2775

- 验证方法：
1. 正常开机，确认一下屏幕能否正常显示，亮灭屏，背光调节是否正常,重启 3 0 次。
2. 异常开机，进入recovery模式时，lcd是否还会有显示。

#3 - 2023-03-03 18:22 - CDTS_TEST 王成

- Priority changed from Normal to High
- Severity changed from Normal to Critical

#4 - 2023-03-06 17:42 - CDTS_Test 吴诗雨

- File 20230306-173926.jpg added
- File 20230306-173908.jpeg added
- Priority changed from High to Normal
- Severity changed from Critical to Normal

【复现结果】

- 1、正常开机，重启30次，正常显示，亮灭屏，亮度调节正常
- 2、异常开机，删除/persist/key和/metadata/vold/*/key后，重启设备进入recovery模式，lcd呈黑屏状态，没有显示

#5 - 2023-03-07 11:04 - 移动测试一组_CDTS 刘强

- Assignee changed from 移动测试一组_CDTS 刘强 to CDTS_Test 吴诗雨

等合入正式版本后，麻烦再次验证，确认没问题后关闭

#6 - 2023-03-07 13:52 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
185110	general/abl/tianocore/edk2	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dulei0503@thundersoft.com
BSP:Display: Disable display in recovery mode[1/2]Check current whether in recovery modeTC-RID: 0301-0100805IssueID: TS-R-DF-116434Change-Id: I0c5170ab4b7ad8d2810b6811d9193b4d25393532			

#7 - 2023-03-07 13:52 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
185107	general/kernel/msm-4.19	Pre_figure_turbox-c2130c-la1.1-vendor-dev	dulei0503@thundersoft.com
BSP:Display: Disable display in recovery mode[2/2]Disable display in recovery modeTC-RID: 0301-0100805IssueID: TS-R-DF-116434Change-Id: I275a4ce9e3cdd6b6d39f1f86f08c3f235aed0ad2			

#8 - 2023-03-07 13:53 - CD BSP-杜磊

- % Done changed from 0 to 100

#9 - 2023-03-08 14:12 - CDTS_Test 吴诗雨
- Status changed from RESOLVED to VERIFIED

【验证版本】FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101.202303080018
【验证结果】
1、正常开机，重启30次，正常显示，亮灭屏，亮度调节正常
2、异常开机（总共重复步骤5次进入recovery模式）
删除/persist/key和/metadata/vold/*/key后，重启设备进入recovery模式，lcd呈黑屏状态，没有显示

#10 - 2023-03-08 14:12 - CDTS_Test 吴诗雨
- Status changed from VERIFIED to CLOSED

Files			
teraterm.log	919 KB	2023-02-22	移动测试一组_CDTS 刘强
20230306-173926.jpg	91.8 KB	2023-03-06	CDTS_Test 吴诗雨
20230306-173908.jpeg	130 KB	2023-03-06	CDTS_Test 吴诗雨