

Figure - Bug #116451

测试 Test-IT # 110867 (New): V1.0测试功能汇总

测试 Test-IT # 110895 (New): AF-V1.0功能测试-桌面

【AF】【EVT】【桌面】部分应用图标周围显示有白边

2023-02-22 15:35 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-02-22
Priority:	Normal	Due date:	2023-03-17
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-APP	Estimated time:	0.00 hour
Target version:	VC1_FSE_0082_20230314		
Need_Info:	--	Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0076.X
Resolution:	FIXED	Degrated:	No
Severity:	Normal	Verified Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101.202303
Reproducibility:	Every time	Fixed Version:	2023-03-03
Test Type:	ST	Root cause:	AOSP问题

Description	
【前提条件】 1、设备已开机 2、本地有视频 【测试步骤】 1、下载一些三方应用 2、查看图表显示 【预期结果】 2、应用图标大小显示一致，无白边 【实际结果】 2、部分应用图标周围显示有白边	

History

#1 - 2023-02-24 10:41 - CD APP-王营
- Due date set to 2023-03-17
#2 - 2023-02-28 14:38 - CDTS-TEST 周婷
- Target version set to VX1_MCE_FSE_0082_20230314
#3 - 2023-03-01 17:46 - CD APP-王宏
- Status changed from New to ASSIGNED
- Assignee changed from CD APP- 王营 to CD APP- 王宏
- % Done changed from 0 to 10
■ Current conclusion
分析中
■ My analysis
此处本应是第三方APP自己去做适配操作，但是他们没做，收集资料如下
https://zhuanlan.zhihu.com/p/394394678
https://blog.csdn.net/qg23001186/article/details/122658475
■ Next action

根据两篇博客做对应修改

#4 - 2023-03-02 14:56 - CD APP-王宏

- % Done changed from 10 to 50

■ Current conclusion

已提交

■ My analysis

根据需求方要求，对于不是正方形的启动图标做拉伸平铺的处理

■ Submit URL

<https://dev.thundercomm.com/gerrit/c/general/platform/frameworks/libs/systemui/+185359>

#5 - 2023-03-02 18:58 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
185359	general/platform/frameworks/libs/syste mui	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	hong.wang_a@thundersoft.com
AF:AdaptiveIcon:Repair the white edge of the startup iconTC-RID: 1201-0206701IssueID: TS-R-BUG-116451Change-Id: la51f69623a2a2d7d38aeb9619e269936220a7a08			

#6 - 2023-03-02 19:00 - CD APP-王宏

- Status changed from ASSIGNED to RESOLVED

- Assignee changed from CD APP-王宏 to CD TEST-方永红

- % Done changed from 50 to 100

- Resolution changed from -- to FIXED

- Degrated changed from -- to No

- Fixed Version set to 2023-03-03

- Root cause set to AOSP问题

#7 - 2023-03-03 18:19 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED

- Verified Version set to FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101.202303030144

3.3

验证通过

#8 - 2023-03-03 18:19 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

#9 - 2023-03-07 13:39 - CD TPM-王祥林

- Target version changed from VX1_MCE_FSE_0082_20230314 to VC1_FSE_0082_20230314

#10 - 2023-09-23 21:44 - IoT scm

Gerrit Merge Information :

--	--	--	--

ID	Project	Branch	Uploader
315370	general/platform/frameworks/libs/syste mui	Pre_figure_turbox-c2130c-la1.1-qssi12 -dev	wujun.wang@thundersoft.com
AF:Adaptivelcon: icon corner adaptationAdapte VX 、 VCTC-RID: 1201-0206701IssueID: TS-R-BUG-116451Change-Id: l8eeecfbd0ff9f06c14a24ab8ab5e99028aff4aa			

#11 - 2023-09-24 12:50 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
315499	general/platform/frameworks/libs/syste mui	Pre_figure_turbox-c2130c-la1.1-qssi12 -release_sorp	wangxl0510@thundersoft.com
AF:Adaptivelcon: icon corner adaptationAdapte VX 、 VCTC-RID: 1201-0206701IssueID: TS-R-BUG-116451Change-Id: l8eeecfbd0ff9f06c14a24ab8ab5e99028aff4aa(cherry picked from commit 0f6581ba36e6cd564bc3b988a4869bf223e2f798)			

Files			
1531.jpg	206 KB	2023-02-22	CD TEST-方永红