

Figure - Bug #116455

测试 Test-IT # 111062 (New): V3.0功能测试

测试 Test-IT # 111069 (New): AF-V3.0--Launcher/SystemUI-小窗模式入口

【AF】【EVT】【小窗模式】时钟小窗部分页面显示异常

2023-02-22 16:08 - CD TEST-方永红

Status:	CLOSED	Start date:	2023-02-22
Priority:	Normal	Due date:	
Assignee:	CD TEST-方永红	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.R.user.01.00.0076.X
Need_Info:	--	Degrated:	--
Resolution:	FIXED	Verified Version:	FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101.202302250116
Severity:	Normal	Fixed Version:	
Reproducibility:	Every time	Root cause:	根据最新的需求,时钟app被删除
Test Type:	ST		
Description			
【测试步骤】			
1、开启闹钟后出现的提示位置			
2、直接打开时钟小窗->进入设置页面->点击一周的第一天->出现的选择框位置			
3、在设置中将时钟样式改为指针->在时钟页面添加多个地区的时间显示->进入recent->点击时钟卡片的小窗安妮->时钟页面显示不完全			
【截图】			
见附件			

History

#1 - 2023-02-24 19:48 - CD FW-鲁凯峰

- Status changed from New to RESOLVED
- Assignee changed from CD FW- 鲁凯峰 to CD TEST-方永红
- Resolution changed from -- to FIXED
- Root cause set to 根据最新的需求,时钟app被删除

■ Current conclusion

问题已经解决

■ My analysis

根据最新的需求,时钟app被删除

■ Submit URL

https://dev.thundercomm.com/gerri/c/general/platform/vendor/thundercomm/apps/app_rm/+/184138

#2 - 2023-02-27 11:08 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101.202302250116

#3 - 2023-02-27 11:08 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED
- % Done changed from 0 to 100

Files			
15462.png	75.5 KB	2023-02-22	CD TEST-方永红
15503.png	79.3 KB	2023-02-22	CD TEST-方永红
Phone-STS40X190078 2023-02-22 16-08-18.mp4	9.13 MB	2023-02-22	CD TEST-方永红