

Figure - Bug #116495

测试 Test-IT # 110961 (New): V2.0功能测试
测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT3】【设置】重复打开"系统WebView许可"页面，页面内容无法加载出来

2023-02-23 16:31 - CD Test赵飞

Status:	CLOSED	Start date:	2023-02-23
Priority:	Normal	Due date:	
Assignee:	CD Test赵飞	% Done:	100%
Category:	CD-FW	Estimated time:	0.00 hour
Target version:		Found Version:	FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2
Need_Info:	--	Degrated:	Yes
Resolution:	FIXED	Verified Version:	
Severity:	Normal	Fixed Version:	2023-02-27
Reproducibility:	Every time	Root cause:	91.xxx 版本 WebView 的问题。
Test Type:	ST		

Description	
【前提条件】 1、设备正常启动 【测试步骤】 1、进入设置 - 关于本机 - 法律信息 - 系统WebView许可 2、点击返回按钮 3、再次进入系统WebView许可页面 【预期结果】 3、页面内容正常被加载出来 【实际结果】 3、第二次进入后，页面内容无法加载出来 【日志】 录屏见附件	

History

#1 - 2023-02-24 18:50 - CD FW-廖涛

- % Done changed from 0 to 80

- Root cause set to 91.xxx 版本 WebView 的问题。

- Current conclusion
- 已处理并验证。
- My analysis
- 91.xxx 版本 WebView 的问题。升级为 95.xxx 版本后运行正常。
- Next action
- 等待分支申请下来提交代码。

#2 - 2023-02-27 10:09 - IoT scm

Gerrit Merge Information :

ID	Project	Branch	Uploader
184379	general/platform/external/chromium-webview	Pre_figure_turbox-c2130c-la1.1-qssi12-dev	tao.liao@thundersoft.com
AF:Settings: Update webview apk to version 95.0.4638.74TC-RID: 1201-0201809IssueID: TS-R-BUG-116495Change-Id: I6da1829f8b2fc4dbc2c18f70118202ead1d899d5			

- #3 - 2023-02-27 10:10 - CD FW-廖涛
- Status changed from New to RESOLVED
 - Assignee changed from CD FW-廖涛 to CD Test赵飞
 - % Done changed from 80 to 100
 - Resolution changed from -- to FIXED
 - Degrated changed from -- to Yes
 - Fixed Version set to 2023-02-27

■ Current conclusion

已处理，代码已入库。

■ My analysis

--

■ Next action

测试验证。

- #4 - 2023-02-28 10:26 - CD Test赵飞
- Status changed from RESOLVED to VERIFIED

验证版本：FlatBuild_HH_MCE_FSE.M.R.user.01.00.0078.C101

验证结果：PASS

- #5 - 2023-02-28 10:26 - CD Test赵飞
- Status changed from VERIFIED to CLOSED

Files			
screen-20230223-162240.mp4	6.37 MB	2023-02-23	CD Test赵飞