

Figure - Bug #116507

测试 Test-IT # 110961 (New): V2.0功能测试  
测试 Test-IT # 111056 (New): AF-V2.0-Launcher/SystemUI----Setting

【AF】【EVT】【设置】蓝牙配对的弹窗下面的勾选选项应该去掉

2023-02-23 18:24 - CD TEST-方永红

|                  |             |                   |                                                 |
|------------------|-------------|-------------------|-------------------------------------------------|
| Status:          | CLOSED      | Start date:       | 2023-02-23                                      |
| Priority:        | Normal      | Due date:         |                                                 |
| Assignee:        | CD TEST-方永红 | % Done:           | 100%                                            |
| Category:        | CD-FW       | Estimated time:   | 0.00 hour                                       |
| Target version:  |             |                   |                                                 |
| Need_Info:       | --          | Found Version:    | FlatBuild_HH_VX1_MCE_FSE.M.D.user.01.00.X101.2  |
| Resolution:      | FIXED       | Degrated:         | No                                              |
| Severity:        | Normal      | Verified Version: | FlatBuild_HH_MCE_FSE.M.D.user.01.00.C101.202302 |
| Reproducibility: | Every time  | Fixed Version:    | 2023-02-24                                      |
| Test Type:       | ST          | Root cause:       | 通讯录同步功能为 AOSP 原有逻辑，需要移除。                        |

Description

【前提条件】

1、设备正常启动

【测试步骤】

1、进入设置  
2、进行蓝牙配对

【预期结果】

2、配对弹框与UI设计一致

【实际结果】

2、配对弹框与UI设计一致  
会出现弹窗并需要勾选访问通讯录和通话记录

【复现率】

3/3

History

#1 - 2023-02-24 18:51 - CD FW-廖涛  
- % Done changed from 0 to 80  
- Root cause set to 通讯录同步功能为 AOSP 原有逻辑，需要移除。

■ Current conclusion  
已处理，代码已提交。

■ My analysis  
通讯录同步功能为 AOSP 原有逻辑，需要移除。已做移除处理。

■ Next action  
等待代码 Review 后入库。

#2 - 2023-02-24 19:38 - CD FW-廖涛

- Status changed from New to RESOLVED
- Assignee changed from CD FW-廖涛 to CD TEST-方永红
- % Done changed from 80 to 100
- Resolution changed from -- to FIXED
- Degrated changed from -- to No
- Fixed Version set to 2023-02-24

■ Current conclusion

已处理，代码已入库。

■ My analysis

--

■ Next action

测试验证。

#3 - 2023-02-24 19:40 - IoT scm

Gerrit Merge Information :

| ID                                                                                                                                                             | Project                                     | Branch                                        | Uploader                 |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------|-----------------------------------------------|--------------------------|
| 184111                                                                                                                                                         | general/platform/packages/apps/Settin<br>gs | Pre_figure_turbox-c2130c-la1.1-qssi12<br>-dev | tao.liao@thundersoft.com |
| AF:Settings: Remove contact checkbox of bluetooth pair dialog.TC-RID: 1201-0201801IssueID: TS-R-BUG-116507Change-Id: I0237cdea6f306776ff162ee8e81fef88e762cb6c |                                             |                                               |                          |

#4 - 2023-02-27 10:52 - CD TEST-方永红

- Status changed from RESOLVED to VERIFIED
- Verified Version set to FlatBuild\_HH\_MCE\_FSE.M.D.user.01.00.C101.202302250116

2.27

验证通过

#5 - 2023-02-27 10:52 - CD TEST-方永红

- Status changed from VERIFIED to CLOSED

Files

|           |        |            |             |
|-----------|--------|------------|-------------|
| 17472.png | 194 KB | 2023-02-23 | CD TEST-方永红 |
|-----------|--------|------------|-------------|